

15-163-00488-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Anschutz Drilling Co Address Union Nat'l Bk Bldg., Wichita,
(Applicant) Ks.

Lease (Farm Name) Stahl Well No. 1

Well Location NW NW NE Sec. 11 Twp. 9 Rge. 18 (EX)-(W)

County Rooks Field Name (if any)

Total Depth 3599' Oil Gas Dry Hole X

Was well log filed with application? Yes. If not, explain:

Date and hour plugging is desired to begin March 25, 1953

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired. (Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

P. S. McCarter Address Box 186, Great Bend, Ks.

Name of Plugging Contractor Braden Drilling Company

Address Union Nat'l Bk Bldg., Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to

Braden Drilling Co Address Union Nat'l Bk Bldg., Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
Wichita, Kansas

[Signature]
Applicant or Acting Agent

Date March 30, 1953

4-1-53

PLUGGING
FILE SEC 11 T 9 R 18W
BOOK PAGE 88 LINE 10



15-163-00488-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

March 30, 1953

Well No. 1
Lease Stahl
Description NE NW NE 11-9-18W
County Rooks
File No. 88-10

Anschutz Drilling Company
709 Union National Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR

F