STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Comparation Commission

WELL PLUGGING RECORD

800 Bitting Building Wichita, Kansas			. C L C	m linas							
NORTH	Location as "NE										
	Lease Owner Jones, Shelburne & Farmer, Inc. Lease Name Charlie Well No. 1										
	1										
	Office Address										
		ell (completed a	-		•						
	Date well comp										
	Application for I										
	Application for p										
	Plugging comme					•					
	Plugging comple					•					
	Reason for aband	donment of well	or producing	g formation	Dry						
		Reason for abandonment of well or producing formation									
	If a producing well is abandoned, date of last production Never Produced										
		obtained from				ore plugging v					
Locate well correctly on above Section Plat	menced?y	res ·		<u></u>							
Name of Conservation Agent who super	ervised plugging of this	well <u>Elde</u>	n Petty								
Producing formation	Do	epth to top	Bottom	1	Total Depth of	Well38					
Show depth and thickness of all water,	, oil and gas formations	s.	·		•						
OTT CAG OR WARRED DECORE	NO .					CASING REC					
OIL, GAS OR WATER RECORD)8			(- my		CASING REC					
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED O					
				8 5/8	1681	Non					
The state of the s											
					T						
				7	•						
				-							
feet for each plug se	n heavy mud	re used, st ate the									
l. Filled hole with 2. Pushed plug to	heavy mud										
l. Filled hole with	heavy mud										
l. Filled hole with 2. Pushed plug to	heavy mud	plug									
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of	n heavy mud 160° ulls on top of pement and dump	plug	of hulls								
1. Filled hole with 2. Pushed plug to 3 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to	n heavy mud 160: 111s on top of Dement and dump	plug ped on top	of hulls								
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1	n heavy mud 160° 111s on top of Dement and dump	plug ped on top	of hulls								
1. Filled hole with 2. Pushed plug to 3 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to	n heavy mud 160° 111s on top of Dement and dump	plug ped on top	of hulls								
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1	n heavy mud 160° 111s on top of 10ement and dump 10ement and dump 10ement and dump	plug ped on top	of hulls								
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2}\) sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2}\) sack	n heavy mud 160° 111s on top of 10ement and dump 10ement and dump 10ement and dump	plug ped on top	of hulls								
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hole 4. Mixed 15 sacks of 1 5. Filled hole to to 1 6. Pushed plug to 1 7. Dumped in ½ sacks of 1 8. Mixed 10 sacks of 1	n heavy mud 160: 111s on top of cement and dump cop chulls. chulls.	plug ped on top ed hole to description is necess	of hulls	1 Same.							
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2} \) sack hole 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2} \) sack 8. Mixed 10 sacks co	n heavy mid 160: alls on top of cement and dump cop chulls. ement and fille Jones, Shelt	plug ped on top ed hole to description is necess purne & Far	of hulls	1 Same.							
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hole 4. Mixed 15 sacks of 1 5. Filled hole to to 1 6. Pushed plug to 1 7. Dumped in ½ sacks of 1 8. Mixed 10 sacks of 1	n heavy mud 160: 111s on top of cement and dump cop chulls. chulls.	plug ped on top ed hole to description is necess purne & Far	of hulls top with	1 Same.							
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in ½ sack 8. Mixed 10 sacks co	h heavy mid 160: 111s on top of Dement and dump top (If additional of the second	plug ped on top ed hole to description is necess purne & Far	top with	1 Same.							
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in ½ sack 8. Mixed 10 sacks co	h heavy mid 160: 111s on top of Dement and dump top (If additional of the second	plug ped on top ed hole to description is necess purne & Far	top with	1 Same.							
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in ½ sack 8. Mixed 10 sacks co	h heavy mid 160: 111s on top of Dement and dump top (If additional of the second	plug ped on top ed hole to description is necess purne & Far	top with	1 Same.	-, ss. her or operator)	of the above-c					
1. Filled hole with 2. Pushed plug to 1 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in ½ sack 8. Mixed 10 sacks co	h heavy mid 160: 111s on top of Dement and dump top (If additional of the second	plug ped on top ed hole to description is necess purne & Far	top with	1 Same.	_, ss. aer or operator) rs herein contain	of the above-coned and the lo					
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2} \) sack hole 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2} \) sack 8. Mixed 10 sacks co	n heavy mud 160: 111s on top of Dement and dump Cop (If additional of the second	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e)	top with	of this sheet) 23-52 Owner) or (owners, and matter)		of the above-c					
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2}\) sack hu 4. Mixed 15 sacks of 5. Filled hole to 1 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2}\) sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, see	n heavy mud 160: alls on top of dement and dump cop (If additional Jones, Shelk Russell, Ka Vera, Coul Vera, Coul vera, Coul the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF wledge of the fi	top with	of this sheet) 23-52 Owner) or (owners, and matter)		of the above-oned and the lo					
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2}\) sack hu 4. Mixed 15 sacks of 5. Filled hole to 1 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2}\) sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, see	n heavy mud 160: alls on top of dement and dump cop (If additional Jones, Shelk Russell, Ka Vera, Coul Vera, Coul vera, Coul the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e)	top with	of this sheet) 23-52 Downer) or (ownents, and matter)		of the above-c					
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2}\) sack hu 4. Mixed 15 sacks of 5. Filled hole to 1 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2}\) sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, see	n heavy mud 160: alls on top of dement and dump cop (If additional Jones, Shelk Russell, Ka Vera, Coul Vera, Coul vera, Coul the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF wledge of the fi	top with	of this sheet) 23-52 Owner) or (ownents, and matter 100. Fac	riner	of the above-coned and the lo					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hole 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1/2 sack 7. Dumped in ½ sack 8. Mixed 10 sacks co Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mid 160: alls on top of cement and dump cop (If additional Jones, Shelt Russell, Ka NSER, COUN NICH, COUN title, Count the same are true and	plug ped on top ed hole to description is necess purne & Far ansas NTY OF (e) weldge of the fide of the fide correct. So he (Signature)	top with	of this sheet) 23-52 Owner) or (ownents, and matter 100. Fac		of the above-coned and the lo					
1. Filled hole with 2. Pushed plug to 1 3. Dumped \(\frac{1}{2}\) sack hu 4. Mixed 15 sacks of 5. Filled hole to 1 6. Pushed plug to 1 7. Dumped in \(\frac{1}{2}\) sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, see	n heavy mid 160: alls on top of cement and dump cop (If additional Jones, Shelt Russell, Ka NSER, COUN NICH, COUN title, Count the same are true and	plug ped on top ed hole to description is necess purne & Far ansas NTY OF (e) weldge of the fide of the fide correct. So he (Signature)	top with	of this sheet) 23-52 Owner) or (ownents, and matter 100. Fac	riner	of the above-oned and the lo					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hole 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1/2 sack 7. Dumped in ½ sack 8. Mixed 10 sacks co Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mid 160: alls on top of cement and dump cop (If additional Jones, Shelt Russell, Ka NSER, COUN NICH, COUN title, Count the same are true and	plug ped on top ed hole to description is necess purne & Far ansas NTY OF (e) weldge of the fide of the fide correct. So he (Signature)	top with	of this sheet) 23-52 Owner) or (ownents, and matter 100. Fac	riner	of the above-oned and the lo					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 4 7. Dumped in ½ sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess purne & Far ansas NTY OF (e) weldge of the fide of the fide correct. So he (Signature)	top with	of this sheet) 23-52 Owner) or (ownents, and matter 100. Fac	riner	52. 00					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 4 7. Dumped in ½ sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e) cowledge of the find correct. So he (Signature) day of	top with	of this sheet) 23-52 owner) or (ownents, and matter 100. Pa	Address) Perryhi	52_ OC Notary F					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to ½ 7. Dumped in ½ sack 8. Mixed 10 sacks co Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess purne & Far ansas NTY OF (e) weldge of the fid correct. So he (Signature) day of	top with	of this sheet) 23-52 owner) or (ownents, and matter 100. Pa	Address) Perryhi	52_ OC Notary F					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 4 7. Dumped in ½ sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e) cowledge of the find correct. So he (Signature) day of	top with ary, use BACK mer, Inc. mployee of cacts, statemed by me Cod.	of this sheet) 23-52 owner) or (ownents, and matter choher	Address) Perryhi	52_ OC Notary F					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack ho 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 1 7. Dumped in ½ sach 8. Mixed 10 sacks co Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that SUBSCRIBED AND SWORN TO before My commission expires April 23.	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e) cowledge of the find correct. So he (Signature) day of	top with ary, use BACK mer, Inc. mployee of cacts, statemed by me Cod.	of this sheet) 23-52 owner) or (ownents, and matter choher	Address) Perryhi	52_ OC Notary F					
1. Filled hole with 2. Pushed plug to 3. Dumped ½ sack hu 4. Mixed 15 sacks of 5. Filled hole to to 6. Pushed plug to 4 7. Dumped in ½ sack 8. Mixed 10 sacks of Name of Plugging Contractor Address STATE OF well, being first duly sworn on oath, above-described well as filed and that	n heavy mud 160: alls on top of cement and dump cop (If additional Jones, Shelk Russell, Ka Vera, cour Viron says: That I have know the same are true and	plug ped on top ed hole to description is necess curne & Far ansas NTY OF (e) cowledge of the find correct. So he (Signature) day of	top with ary, use BACK mer, Inc. mployee of cacts, statemed by me Cod.	of this sheet) 23-52 owner) or (ownents, and matter ctoher	Address) Perryhi	52_ Notary F					

1.01m	1002 A		OP	ER	ATC)R	Jor	10	s,	Shel	burn	.е &	Farme	r,	Inc	. [
	. •		ADI	DR	ESS		Rı	15	se	11, K	ansa	s				
	640 A	Acres V			. c c	OUN?	ry. Gi	ra.	ha	m sec	.15	Т	we l	.05	RGE	21W
		П		٦	ÇO	MPA	ANY (OPE	RA	ting Jo	nes,	She	lburn	ie &	Fa	rmer
160			160							Ru						
			11	_						harli						
		\downarrow	++	4						10-6						
	++	+		\dashv						ODUCTIO						
160			160	十	-											
			11	7						to sea le						
L	ocate wel	l corr	ectly							ELL (Oil,						
					· · · ·											·
	Nam		•		F	OIL OR GAS SANDS OR ZON						Vame	То			
,			-		+-		+-		_	4	!	-		+	rom	
2					+		1		-	5			<u> </u>		· · · · · · · · · · · · · · · · · · ·	
3									_	6 ,			•			1
	P	erior	sting l	leco	rd II	Ару	,					Sì	ot Record	l .	-	
Formation From					To No. of Shots Fo				Formati	on	From	То	Size	e of Sho		
1			4		<u> </u>	_			:				1	ļ		
		•			ļ	_				<u> </u>			. **	ļ	4-	
	 		Щ.		ب ــــــــــــــــــــــــــــــــــــ			LAS	ING	RECORD)		1		1	
	· . · ·	•	Amoun	t Se	ıt.	···				- ILCOND		Amou	nt Pulled	Pac	ker R	ecord
Size	Wt.		Thds.	,	ake		Ft.	Ir	ı. [Ft.	ln.	Size	Length	 		Make
5/	3 2/	Ţ	Ŕ	ī	W	-	168									
			4					L		4				<u> </u>	•	
	1					ļ.,		L			<u> </u>			<u> </u>		<u> </u>
iner I	Record:	Amou	int		•		Kind				Top		В	ottom		
		C. 4						1111		AND MUL	T	T		- i -		
Size Amount Set Ft. In.			Sacks Cement		Gal.		mical Make		Method of Cementing		Amount		Muddii Metho			sults Note)
5/8	168		7.0					\dashv			†			-		
2/0	104		10	~4		_	· · · · · · · · · · · · · · · · · · ·	\dashv			1					
lote: \	What me	thod	was 1	used	i to i	prote	ect sor	ıds	if c	outer strin	gs wer	e pulle	d?			
											<u></u>					
NOTE:	Were b	ottom	hole	pluç	78 US	ed?			lf s	o, state ki	nd, der	oth set	and result	s obta	ined	
										s used						
										_Cable 1						
	ig		nd from	m			_loet	to_		te	et, cond	trom_		1661	10	
ype .	<u> </u>		-							DUCTON						
Describ	e initial	test	: whet	her	by f					DUCTION ing or cas		by pu	nping			·. · ·
										-		-		_		
mount	of Oil	Produ	ction			bb	ls. Siz	e 0	í cì	noke, if an	ıy	L	ength of	lest		Wate
Produc	ion		_bbls.	Gro	vity	of c	oi L		7	Type of P	ın qanı	pump i	s used, d	escribe		

Formation	Top	Bottom	Formation	Top	Bottom	
Inc.		·				
Cellar	0	146				
Shale	146		,]	
² Sand	850	1400				
Shale	1400					
Shale & Shells	1600				1 -	
Anhydrite	1680	1725				
Shale & Shells	1725	2105				
Shale & Lime	2105	2880		1		
Lime & Shale	2880	3460	* * * * * * * * * * * * * * * * * * * *			
Lime34	3460	3710	, • • • • • • • • • • • • • • • • • • •	1		
Lime & Shale	3710	B805			ŀ	
Conglomerate	\$805	β809				
Arbuckle 380	3809	3822		1	,	
					-	
			TOPS:	1.		
	-	`		1	1.	
			ation 2203 R. B.			
\bigcirc	[ner 3444			
Krcd	1		KXXXXXXX	1		
			as City 3483	1		
\$10-23-1957	,		kle 3809			
10 20 1 10°			Depth 3832	-4		
	1,	D &		1		
<u>.</u>						
				1 1		
PLUGGIA SEC 45 T/20					1 1	
FRE TUGGIA	Į.	+-			1.	
ACCO PER 120		1			1	
PAGE AS			,			
MCCC PACIFIE	رعا					
	-	1				
and man.		1				
3 Maye						
		1				
the first of the second				1	1	

I, the undersigned, being first duly sworn upon ooth, state that this well record is true, correct and complete according to the records of this office and to the best of my knowledge and belief.

Subscribed and sworn to before me this 20thay of October

My Commission expires April 23, 1956