4-071008

TO: API number: 15-179-21,046-00-00 STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING **SW SE NW** /4 SEC. 14 , 09 S, 27 W 200 COLORADO DERBY BUILDING 2970 ___ feet from S section line WICHITA, KANSAS 67202 3630 feet from E section line Operator license# 03655 Lease Popp well # 1 Operator: Staab Energy & Leasing County Sheridan Address: 2514 Haney Drive _____ Well total depth <u>4120</u> feet Hays, Kansas 67601 Conductor Pipe: 0 inch 0 0 feet Norman G. Staab Surface pipe 8 5/8 Inch @ 264 feet Aband. oil well ____, Gas well ____, Input well ____, SWD ____, D & A _X Plugging contractor: Shields Drilling Company, Inc. License# -Address: Russell, Kansas 67665 Company to plug at: Hour: P.M. Day: 11 Month: October Year: 92 Plugging proposal received from: Bert Berry Company: Shields Drilling Company, Inc. Phone: 913-628-1326 Were: 8 5/8" - 264' S.P. cwc. with 190 sx. - 2% qel. - 3% c.c. Cemented by Allied Cementing. L.K.C. Well. No arbuckle. Elev. 2736'. Anhy. 2332'. Mud condition - 50 vis. - 9.2 weight - 10-12 water loss. No circulatin problems. Proposal 200 sx. 60/40 pozmix - 6% gel - 1 sx. flocele. Spot with drill stem, circulate hole, heavy mud between all plugs. 25 sx. cement @ 2340' - 100 sx. cement @ 1486' with 1 sx. flocele mixed in - 10 sx. cement @ 40' - 15 sx. in rathole circulate - 10 sx. in mousehole circulate. Plugging Proposal Received by: Marion J. Schmidt Plugging operations attended by agent? All[], Part[], None[X] Completed: Hour: 6:00P.M., Day: 11 , Month: October , Year: 92 Actual plugging report: Shields ordered 200 sx. 60/40 pozmix - 6% qel. and one sack of flocele. Spotted and displaced cement through drill stem, circulated hole. STATE CORPORATION COMMISSION 1st. pluq @ 2340' w/25 sx. cement. 2nd. plug @ 1486' w/100 sx. cement and 1 sx. flocele. 3rd. pluq @ 300' w/40 sx. cement. 15 sx. in rathole (circulate) - 10 sx. in mousehole (circulate) of the local control of the l Wichita, Kansas Remarks: <u>Cemented by: Allied Cementing</u> Condition of casing(in hole):GOOD X BAD Anhy.plug:YES Bottom plug(in place):YES X ,CALC ,NO Dakota plug:YES X ,NO Plugged through TUBING X , CASING . Elevation: 2736 did not[X] observe the plugging. (agent) Form CP-2/3