KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING APPLICATION

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

Address: P.O. Box 18596 State: Oklahoma	Sec. 25 Twp. 28 S. R. 34W East West Haskell It outside section corner) Line of Section (Not Lease Line) Vater Supply Well Other: Cemented with: Cemented with: 250 Sacks Cemented with: 250 Sacks
Well Operator: Chesapeake Operating, Inc. Address: P.O. Box 18596 State: Oklahoma Lease: Lemon Well #: 1-25 Spot Location / QQQQ County: 4820 3001 Feet (in exact footage) From North / South (from nearest footage) Check One: Oil Well	City: Oklahoma City Contact Phone: (405) 879 - 9375 Sec. 25 Twp. 28 S. R. 34W East West Haskell thoutside section corner) Line of Section (Not Lease Line) at outside section corner) Line of Section (Not Lease Line) Vater Supply Well Other: Sacks Cemented with: 250 Sacks Cemented with: 250 Sacks
Address: P.O. Box 18596 State: Oklahoma	City: Oklahoma City Contact Phone: (405) 879 - 9375 Sec. 25 Twp. 28 S. R. 34W East West Haskell thoutside section corner) Line of Section (Not Lease Line) at outside section corner) Line of Section (Not Lease Line) Vater Supply Well Other: Sacks Cemented with: 250 Sacks Cemented with: 250 Sacks
State: Oklahoma Zip Code: 73154-0496	Contact Phone: (405) 879 - 9375 Sec. 25 Twp. 28 S. R. 34W ☐ East ✓ West Haskell It outside section corner) Line of Section (Not Lease Line) It outside section corner) Line of Section (Not Lease Line) Vater Supply Well ☐ Other: Sacks Cemented with: 250 Sacks Cemented with: 250 Sacks
Spot Location / QQQQ County: 4820 3007 Feet (in exact footage) From North / South (from nearest 4820 2 72 Feet (in exact footage) From From East / West (from nearest Check One: Oil Well Gas Well D&A Cathodic W SWD Docket # Bet at: Conductor Casing Size: Set at: Set at: 735'	Haskell It outside section corner) Line of Section (Not Lease Line) It outside section corner) Line of Section (Not Lease Line) Vater Supply Well Cemented with: Sacks Cemented with: 250 Sacks Cemented with: 250 Sacks
Feet (in exact footage) From North / South (from nearest 4820 272 Feet (in exact footage) From From East / West (from nearest Check One: Oil Well Gas Well D&A Cathodic W SWD Docket # Feet (in exact footage) From From From From From From From From	t outside section corner) Line of Section (Not Lease Line) It outside section corner) Line of Section (Not Lease Line) Vater Supply Well Cemented with: Sacks Cemented with: 250 Sacks Cemented with: Sacks
Feet (in exact footage) From North / South (from nearest decay) North / South (from nearest decay) South (from nearest decay) North / South (from nearest decay) South (from nearest decay) North / South (from nearest decay) South (from nearest decay) South (from nearest decay) South South decay) South decay South South decay South South decay South South decay) South decay South South decay South South decay South South South decay South South South South decay) North / South (from nearest decay) South South (from nearest decay) South	t outside section corner) Line of Section (Not Lease Line) It outside section corner) Line of Section (Not Lease Line) Vater Supply Well Cemented with: Sacks Cemented with: 250 Sacks Cemented with: Sacks
Check One: Oil Well Gas Well D&A Cathodic W SWD Docket # ENHR Docket # Conductor Casing Size: Set at: 735' Surface Casing Size: 8 5/8" Set at: 735'	Other: Sacks
Check One: Oil Well Gas Well D&A Cathodic W SWD Docket # Set at: Surface Casing Size: Set at:	Cemented with: Sacks Cemented with: 250 Sacks Cemented with: 250 Sacks
Conductor Casing Size: Set at: Surface Casing Size: 8 5/8" Set at: 735'	Cemented with:
Surface Casing Size: 8 5/8" Set at: 735'	Cemented with: 250 Sacks Cemented with: 250 Sacks
	Cemented with: 250 Sacks
Production Casing Size 4 1/2" Set at. 5,400'	
. , outdoner, Outling Oizo, Obt at	shut-in: 4 618 - 4 626 - shut-in: 4 172 - 4 176 -shut-in
List (ALL) Perforations and Bridgeplug Sets: 5,307 - 5,318 - plugged; 5,220 - 5,240 - 9	
Elevation: (G.L. / K.B.) T.D.: 5,428 PBTD: 5,281 Anhy	ydrite Depth:
	(Stone Corral Formation) k in Hole
Proposed Method of Plugging (attach a separate page if additional space is needed): See att	tached page.
	RECEIVED KANSAS CORPORATION COMMIS
Is Well Log attached to this application as required? Yes No Is ACO-1 filed?	✓ Yes
If not explain why?	CONSERVATION DIVISION WICHITA, KS
Plugging of this Well will be done in accordance with K.S.A. 55-101 <u>et. seq</u> . and the R	Rules and Regulations of the State Corporation Commission.
List Name of Company Representative authorized to be in charge of plugging operations:	
Bud Neff, Production Superintendent	Phone: (620) 277 - 0803 ext. 11
Address: 4532 W. Jones Avenue	City / State: Garden City, KS 67846
Plugging Contractor: Allied Cementing Co., Inc.	KCC License #:
Address:	
Proposed Date and Hour of Plugging (if known?):	
Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Age	ent j
Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent: Date: 8/21/08 Authorized Operator / Agent: Dung Howel	el, ber Aletha Dembre-Kinc

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Sirst 1

Procedure:

Plug and Abandon:

- 1. MIRU workover unit. MIRU wireline, PU 4 ½" CIBP, RIH and set CIBP at ±4,100". Spot 2 sacks of cement on CIBP. Cut off wellhead, and weld on pulling sub. Perform free-point inspection and cut off casing at free-point.
- 2. TOOH laying down 4 1/2" casing in singles, send recovered casing in for credit.
- 3. PU 2-3/8" tubing, TIH open-ended to 4 ½" casing stub. Displace hole with 9.0 ppg plugging mud. MIRU cementing services, mix and pump 50 sack cement plug.
- 4. PU and land EOT at ±750' and mix and pump ±25 sacks of cement.
- 5. PU to ±60' and mix and pump 25 sacks of cement. RDMO cementing services.
- 6. Cut off 8 5/8" casing 4' below ground level and weld on cap. Clean up location. RDMO workover unit. Send tubing and rods in for evaluation and credit.

RECEIVED KANSAS CORPORATION COMMISSION

AUG 2 2 2008

CONSERVATION DIVISION WICHITA, KS



Kathleen Sebelius, Governor Thomas E. Wright, Chairman Michael C. Moffet, Commissioner Joseph F. Harkins, Commissioner

NOTICE OF RECEIPT OF WELL PLUGGING APPLICATION (CP-1)

CHESAPEAKE OPERATING, INC. 6200 N WESTERN AVE PO BOX 18496 OKLAHOMA CITY, OK 73118-1046 September 16, 2008

Re: LEMON #1-25

API 15-081-20054-00-01

25-28S-34W, 3007 FSL 272 FEL HASKELL COUNTY, KANSAS

Dear Operator:

This letter is to notify you that the Conservation Division has received your plugging proposal, form CP-1, for the above well and has reviewed the proposal for completeness. The central office will now forward your CP-1 to the district office listed below for review of the proposed plugging method. Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113(b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit in accordance with K.A.R. 82-3-600.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well. This notice in no way constitutes authorization to plug the above well by persons not having legal rights of ownership or interest in the well.

This notice is void after March 15, 2009. The CP-1 filing does not bring the above well into compliance with K.A.R. 82-3-111 with regard to the Commission's temporary abandonment requirements.

Sincerely,

Steve Bond

Production Department Supervisor

District: #1 210 E Frontview, Suite A Dodge City, KS 67801 (620) 225-8888