

15-193-20045-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION

FEB 13 1973

CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner John O. Farmer, Inc.

Address Box 352, Russell, Kansas 67665

Lease (Farm Name) Fellhoelter Well No. #1

Well Location C SW NE Sec. 34 Twp. 10S Rge. 31W (E) (W)

County Thomas Total Depth 4657 Field Name

Oil Well Gas Well Input Well SWD Well Rotary D & A x

Well Log filed with application as required yes

Date and hour plugging is desired to begin February 8, 1973 9:30 p.m.

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Dale Buchheister Address 207 N. Washington, Plainville, Ks.

Plugging Contractor John O. Farmer, Inc. License No.

Address Box 352, Russell, Kansas

Invoice covering assessment for plugging this well should be sent to:

Name John O. Farmer, Inc.

Address Box 352, Russell, Kansas 67665

and payment will be guaranteed by applicant or acting agent.

Signed: *John O. Farmer* Geologist
Applicant or Acting Agent

Date: February 12, 1973

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

February 12, 1973

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Fellhoelter
Description	C SW NE 34-10-31W
County	Thomas
Total Depth	4658'
Plugging Contractor	Company Tools

John O. Farmer, Inc.
Box 352
Russell, Kansas 67665

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

J. Lewis Brock
J. Lewis Brock, Administrator

Mr. W. L. Nichols P.O. Box 157 Morland, Kansas 67650
is hereby assigned to supervise the plugging of the above
named well.