SEP 2 7 1991

FORM CP-2/3 Rev. 01-84 Joan Finney Governor

Jim Robinson Chairman

Keith R. Henley Commissioner

Rachel C. Lipman Commissioner

Judith McConnell Executive Director

Brian J. Moline General Counsel



Kansas Corporation Commission

MEMO

TO: Bill Bryson

FROM: Don Butcher

RE: Field Notes on Murfin Ahrens #1

SW 33-10-33

DATE: June 26, 1991

June 23, 1991 - Sunday - 9:25 A.M.

Randy Farr-Murfin- lost radioactive tool in hole on Ahrens Lease in C W/2 SW 33-10-33 Thomas County-1320 S. Line 4620 East Line. Lost the two arms with a Gamma Source and a Neutron Source (fell to bottom at 4780') Called Norb Windholz-not home; called Mike Cochran-not home; called Mike Larson-gave me Harold Spiker's name-not home. Mike Larson called me-he got a hold of Gerald Allen-called G. Allen-He was at his office-called Jerry at his office-explained situation-He gave me needed information including plug method. Randy Farr called back-gave him verbal instructions for Bottom Plug-with Radioactive Source-100' hard cement with whipstock on top. I designed plug using 50 common cement-10 sx. of frac sand and 2% calcium chloride-had other conversations with Jerry and Mike and Randy until 2:00 A.M.-keeping-monitoring of mud in operation and checking on methods to be used in recovery attempts-used junk basket (against my judgement)-didn't work but didn't break tool-

June 24, 1991 - Monday - 6:30 A.M.

Left for Monument-on location about 8:30 A.M.-mud okbasket on surface with two bent teeth-waited most of the day on decision to try 2nd attempt-to recover(did not)lost tool located at 4780'. Ran drill stem to 4775' and cemented with 50 sx. common-10sx. frac sand-2% calcium chloride-12 boxes (4" x 4" x 6" size) of red cement dye and 3 gallons red latex. Cement- calculated to be 65 cu. ft. with a calculated fill of 193' displaced cement with heavy mud to balance plug in hole. Plugging started at 3:00 P.M. Plug down at 3:15 P.M. - let cement set for 4 hours (till 7:30 P.M.) and tagged with drill stem at 4612' - rigged 6' x 6" with 45 decree angle drill collar (whipstock device) to wire line for placement.

Started pulling drill stem. I left location 8:30 P.M. Randy Farr called in-reported cement tagged with whipstock at 4584'-giving 191 feet cement. Whipstock set at 4580.

Cansas Corporation Commission
District Office No. 4
2301 E. 13th
Hays, KS 67601
(913) 628 - 1200

Field Supervisor - Don Butcher