## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

The state of the s	The second secon
Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Missi	on Woods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: ( 620 ) 627 - 2499
Permit Number (API No. if applicable): 15-125-31366-0000	Lease Name & Well No.: Smith 10-28
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW _ SE
Settling Pit	Sec. 28 Twp. 31S R. 17 V East West
Workover Pit Haul-Off Pit	1978 Feet from North / South Line of Section
<u></u>	1978 Feet from 🗸 East / West Line of Section
	Montgomery County
Date of closure: 11/19/2007  Was an artificial liner used?	
	of the pit contents?
	RECEIVED  KANBAS CORPORATION COMMISSION
Self-Sealing Pit	pecsiVFD
Self-Sealing Pit  Abandonment procedure of pit:	RECEIVED  KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION
Self-Sealing Pit	RECEIVED KANSAS CORPORATION COMMISSION DEC 0 5 2007
Self-Sealing Pit  Abandonment procedure of pit:	RECEIVED  KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is Agent	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), to the best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), to the best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), to the best of his /her knowledge and belief.  Signature of Applicant or Agent  ay of November 1, 2007
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANBAS CORPORATION COMMISSION  DEC 0 5 2007  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), to the best of his /her knowledge and belief.  Signature of Applicant or Agent