## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Address: 1625 Broadway, Suite 2200, Denver, CO 80202  Contact Person: Jennifer Barnett Phone Number: ( 303 ) 228 - 4235  Permit Number (API No. If applicable): 15-023-20945-0000 Lease Name & Well No. Zweygardt 12-32  Type of Pit:    Emergency Pit   Burn Pit   Section (OQQQ):   SW NW   Section Pit   S	Operator Name: Noble Energy, Inc.	License Number: 33190
Permit Number (APP No. If applicables): 15-023-20945-0000  Lease Name & Well No. Zweygardt 12-32  Type of Pit:    Emergency Pit   Burn Pit   Settling Pit   Sec. 32 Twp. 35 R. 41   East   West Line of Section (2000):	Operator Address: 1625 Broadway, Suite 2200, Denver, CO 80202	
Type of Pilt:	Contact Person: Jennifer Barnett	Phone Number: ( 303 ) 228 - 4235
SW NW   Sec. 32 Twp 35 R 41   Seat   West   Seat   Se	Permit Number (API No. if applicable): 15-023-20945-0000	Lease Name & Well No.: Zweygardt 12-32
Settling Pit   Drilling Pit   Sec. 32 Twp. 3S R. 41   East   West   2140' Feet from   North / South Line of Section   1250' Feet from   Rest / West Line of Section   Cheyenne   County	Type of Pit:	Pit Location (QQQQ):
Workover Pit	Emergency Pit Burn Pit	<u>sw</u> _ <u>nw</u>
Date of closure: 5/13/2008  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Sealed with clay soil, native and fresh mud.  RECEIVED  KANSAS CORPORATION COMMISSION  MAY 2 8 2008  Abandonment procedure of pit:  Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backfill.  The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc. (Co.).  a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Signature of Applicant or Agent  Applicant or Agent  My Commission Expires Aug. 20, 2008	Settling Pit	Sec. 32 Twp. 3S R. 41 East West
Date of closure: 5/13/2008  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Sealed with clay soil, native and fresh mud.  RECEIVED  KANSAS CORPORATION COMMISSION  MAY 2 8 2008  Abandonment procedure of pit:  Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backful.  The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc. (Co.). a duly authorized agent, that all information shown hereon is true and correct to the best of his firer knowledge and belief.  Signature of Applicant or Agent  My Commission Expires Aug. 20, 2008	Workover Pit Haul-Off Pit	2140' Feet from V North / South Line of Section
Date of closure: 5/13/2008  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Sealed with clay soil, native and fresh mud.  RECEIVED KANSAS CORPORATION COMMISSION  MAY 2 8 2008  Abandonment procedure of pit:  Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backfull.  The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc. (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Signature of Applicant or Agent  My Commission Expires Aug. 20, 2008		1250' Feet from East / West Line of Section
Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Sealed with clay soil, native and fresh mud.  RECEIVED KANSAS CORPORATION COMMISSION  MAY 2 8 2008  Abandonment procedure of pit:  Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backfull.  The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc. (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Signature of Applicant or Agent  Was an artificial liner used?  NAY 2 8 2008  Abandonment procedure of pit:  Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backfull.  Signature of Applicant or Agent  Signature of Applicant or Agent  Applicant or Ag		<u>Cheyenne</u> County
The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Signature of Applicant or Agent  My Commission Expires Aug. 20, 2008	Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Sealed with clay soil, native and fresh mud.  RECEIVED KÄNSÄS ĈORPORATION COMMISSION	
The undersigned hereby certifies that he / she is Permit Representative for Noble Energy, Inc (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Substant and sworn to me on this		KÄNSÄS CORPORATION COMMISSION
a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.  Signature of Applicant or Agent  Substant and sworn to me on this   My Commission Expires Aug. 20, 2008		KÄNSÄS CORPORATION COMMISSION MAY 2 8 2008
Signature of Applicant or Agent  Substant of Applicant or Agent  My Commission Expires Aug. 20, 2008		KÄNSÄS CORPORATION COMMISSION MAY 2 8 2008
Substant d and sworn to me on this 2 th day of May My Commission Expires Aug. 20, 2008	Drill cuttings are stirred with a trac-hoe, allow liquids to ex	MAY 2 8 2008  vaporate, let cuttings dry, and backful.
My Commission Expires Aug. 20, 2008	Drill cuttings are stirred with a trac-hoe, allow liquids to extend the state of th	WAY 2 8 2008  Waporate, let cuttings dry, and backful.  Ve for Noble Energy, Inc. (Co.),
my Commission Expires:	The undersigned hereby certifies that he / she is Permit Representation a duly authorized agent, that all information shown hereon is true and correct to the substant of the substant	MAY 2 8 2008  vaporate, let cuttings dry, and backfull.  ve for Noble Energy, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  Notary Public
	The undersigned hereby certifies that he / she is Permit Representation a duly authorized agent, that all information shown hereon is true and correct to the substant of the substant	WAY 2 8 2008  Waporate, let cuttings dry, and backful.  We for Noble Energy, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  Notary Public