KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Black Diamond Oil, Inc.	License Number: 7076
Operator Address: P.O. Box 641 Hays, KS 67601	
Contact Person: Kenneth Vehige	Phone Number: (785) 625 - 5891
Permit Number (API No. if applicable): 15-065233480000	Lease Name & Well No.: Andreson A #15
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>S/2</u> <u>NE</u> <u>SW</u>
Settling Pit	Sec. 16 Twp. 9 R. 21 ☐ East
Workover Pit Haul-Off Pit	1650 Feet from North / South Line of Section
	1980 Feet from East / West Line of Section
	Graham County
Date of closure: 5-8-2008 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Sealed with clay soil, native & fresh mud	
Sealed with clay soil, native & fresh mud	
Sealed with clay soil, native & fresh mud	RECEIVED KANSAS CORPORATION COMMISSION
Sealed with clay soil, native & fresh mud Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION AUG 2 9 2008
	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry & back	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION WICHITA, KS forBlack Diamond Oil, Inc. (Co.),
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry & back The undersigned hereby certifies that he / she is	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION WICHITA, KS forBlack Diamond Oil, Inc. (Co.),
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry & back The undersigned hereby certifies that he / she is	KANSAS CORPORATION COMMISSION AUG 2 9 2008 CONSERVATION DIVISION WICHITA, KS forBlack Diamond Oil, Inc. (Co.),
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry & back The undersigned hereby certifies that he / she is	AUG 2 9 2008 fill CONSERVATION DIVISION WICHITA, KS Black Diamond Oil, Inc. (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allow liquid contents to evaporate, let cuttings dry & back The undersigned hereby certifies that he / she is	AUG 2 9 2008 fill CONSERVATION DIVISION WICHITA, KS Black Diamond Oil, Inc. (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent