## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

| Operator Name: Rosewood Resources, Inc.   | License Number: 33019  |
|---|--|
| Operator Address: RR 1, Box 206, St. Francis, KS 67756-9789   |  |
| Contact Person: Tom W. Roelfs   | Phone Number: ( 970 ) 324 - 1686   |
| Permit Number (API No. if applicable): 15-181-20537-00 0  | Lease Name & Well No.: Philbrick 42-09   |
| Type of Pit:  | Pit Location (QQQQ):   |
| Emergency Pit Burn Pit  | NE SW SE NE  |
| Settling Pit ✓ Drilling Pit   | Sec. 9 Twp. 9S R. 40W ☐ East ✓ West  |
| ☐ Workover Pit ☐ Haul-Off Pit   | 2133 Feet from North / South Line of Section   |
|   | 698 Feet from 🗸 East / West Line of Section  |
|   | SHERMAN County   |
| 9 15 2009   |  |
| Date of closure: 8-15-2008  |  |
| Was an artificial liner used? ☐ Yes ☑ No  |  |
| If no, how were the sides and bottom sealed to prevent downward migration of the  | pit contents?  |
| Clay/Bentonite barrier from drilling fluids.  |  |
| ,   |  |
| ,   |  |
| ,   |  |
|   | RECEIVEL<br>KANSAS CORPORATION   |
| Abandonment procedure of pit:   | TO WATION COM MISSIO   |
|   | OCT 2 1 2008   |
| Abandonment procedure of pit:   | OCT 2 1 2008   |
| Abandonment procedure of pit:   | OCT 2 1 2008   |
| Abandonment procedure of pit:   | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KS  |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.   | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KS  Rosewood Resources, Inc. (Co.).   |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foreman   | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KS  Rosewood Resources, Inc. (Co.).   |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foreman   | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KS  Rosewood Resources, Inc. (Co.).   |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foreman   | OCT 2 1 2008  CONSERVATION DIVIS. WICHITA, KS  To Rosewood Resources, Inc. (Co.), the best of his /her knowledge and belief.   |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foreman a duly authorized agent, that all information shown hereon is true and correct to the   | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KE  To Rosewood Resources, Inc. (Co.), the best of his /her knowledge and belief.  Signature of Applicant or Agent          |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foremal a duly authorized agent, that all information shown hereon is true and correct to the Subscribed and sworn to me on this day of | OCT 2 1 2008  CONSERVATION DIVISION WICHITA, KS  The for Rosewood Resources, Inc. (Co.), the best of his /her knowledge and belief.  Signature of Applicant or Agent     |
| Abandonment procedure of pit:  Pit was allowed to air dry, then backfilled.  The undersigned hereby certifies that he / she is Production Foreman a duly authorized agent, that all information shown hereon is true and correct to the   | OCT 2 1 2008  CONSERVATION DIVIS. WICHITA, KS.  Rosewood Resources, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  Notary Public |