KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Brungardt Oil & Leasing, Inc.	License Number: 3956
Operator Address: P.O. Box 871, Russell, KS 67665	
Contact Person: Gary L. Brungardt	Phone Number: (785) 483 - 4975
Permit Number (API No. if applicable): 15-141-20369-0000	Lease Name & Well No.: Koelling C #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	sw sw nw
Settling Pit	Sec. 30 Twp. 10 R. 14 East West
Workover Pit Haul-Off Pit	1990 Feet from North / South Line of Section
	590 Feet from ☐ East / ✓ West Line of Section
	Osborne County
Date of closure: 3/7/08 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Drilling mud.	
Drawing mad.	ľ
	RECEIVED KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION MAR 3 1 2008 CONSERVATION DIVISION
	KANSAS CORPORATION COMMISSION MAR 3 1 2008
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION MAR 3 1 2008 CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION MAR 3 1 2008 CONSERVATION DIVISION
Abandonment procedure of pit: Pits allowed to dry. Filled with excavated dirt	KANSAS CORPORATION COMMISSION MAR 3 1 2008 CONSERVATION DIVISION WICHITA, KS forBrungardt Oil & Leasing, Inc(Co.),
Abandonment procedure of pit: Pits allowed to dry. Filled with excavated dirt The undersigned hereby certifies that he / she is President	MAR 3 1 2008 CONSERVATION DIVISION WICHITA, KS for Brungardt Oil & Leasing, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Pits allowed to dry. Filled with excavated dirt The undersigned hereby certifies that he / she is President	MAR 3 1 2008 CONSERVATION DIVISION WICHITA, KS Brungardt Oil & Leasing, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Pits allowed to dry. Filled with excavated dirt The undersigned hereby certifies that he / she is President	MAR 3 1 2008 CONSERVATION DIVISION WICHITA, KS for Brungardt Oil & Leasing, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Pits allowed to dry. Filled with excavated dirt The undersigned hereby certifies that he / she is	MAR 3 1 2008 CONSERVATION DIVISION WICHITA, KS Brungardt Oil & Leasing, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent