

01053-00-00
15-051-~~18650-00-00~~

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Leben Drilling, Inc. Address 905 Central Bldg., Wichita, Kansas
(Applicant)

Lease (Farm Name) Cress #1 Well No. 1

Well Location NW NE SE Sec. 12 Twp. 11S Rge. 17W (X) (W)

County Ellis Field Name (if any) Bemis-Shutts

Total Depth 3336 Oil Gas Dry Hole X

Was well log filed with application? yes If not, explain: _____

Date and hour plugging is desired to begin 11-20-57 @ 4:30 p.m.

Plugging of the well will be done in accordance with the Rules and Regulations of
the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Mr. P. H. Jackson, Box 368 Address Great Bend, Kansas

Plugging Contractor Leben Drilling, Inc.

Plugging Contractor's License No. _____

Address 905 Central Bldg., Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Leben Drilling, Inc. Address 905 Central Bldg., Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
11-27-1957
NOV 27

CONSERVATION DIVISION
Wichita, Kansas

Frank Hamlin
Applicant or Acting Agent

Date November 20, 1957

PLUGGING	
FILE	SEC. <u>12</u> T. <u>11</u> R. <u>17W</u>
BOOK	PAGE <u>63</u> LINE <u>31</u>

STATE OF KANSAS
State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas
November 25, 1957


Well No.	1
Lease	Cress
Description	1/4 1/4 SE 12-11-17W
County	Ellis
File No.	63-31

Loben Drilling, Inc.
905 Central Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas Ph. 4-3218

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor