KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Lester Scheuneman	License Number: 6168
Operator Address: 27800, Pleasant Valley Rd. Wellsvill	e E Kansas, 66092
Contact Person:	Phone Number: (785) 883 - 4621
Permit Number (API No. if applicable): 121-28334-0000	Lease Name & Well No.: Boyscout B-1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NE</u> - <u>NE</u> - <u>SW</u>
Settling Pit X Drilling Pit	Sec. 14 Twp. 17 R. 21 X East West
Workover Pit Haul-Off Pit	2555 Feet from North / XX South Line of Section
	2876 Feet from 🖾 East / West Line of Section
	County
Date of closure: 8-15-07	
Was an artificial liner used? Yes X No	
If no, how were the sides and bottom sealed to prevent downward migration of the	e pit contents?
1	
clay	
clay	
clay	RECEIVED
	RECEIVED KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	
Abandonment procedure of pit: let dry and pushed in.	KANSAS CORPORATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION JAN 2 8 2008
Abandonment procedure of pit: let dry and pushed in.	KANSAS CORPORATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he / she isOwner/ope	KANSAS CORPORATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS PA 402 for 600, (Co.),
Abandonment procedure of pit: let dry and pushed in.	KANSAS CORPORATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS PA 402 for 6 (Co.),
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he / she isOwner/ope	CONSERVATION DIVISION LAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS PA 15 (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he / she isOwner/ope	LANSAS CORPORATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he / she isOwner/ope	CONSERVATION COMMISSION JAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS PA 15 (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he she is	LAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS CEA 102 for 15 (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent Of CAMORY 2008
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he she is	CONSERVATION DIVISION LAN 2 8 2008 CONSERVATION DIVISION WICHITA, KS CLAYOL for his /her knowledge and belief. Land Chamber Signature of Applicant or Agent
Abandonment procedure of pit: let dry and pushed in. The undersigned hereby certifies that he she is	CONSERVATION DIVISION WICHITA, KS CALLO (Co.), the best of his /her knowledge and belief. Chameron Signature of Applicant or Agent Notary Public KITARY PUBLIC - State of Kansas BRENDA S. OLSON