## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

| Operator Name: OXY USA Inc.   | License Number: 5447   |
|---|--|
| Operator Address: P. O.Box 2528, Liberal KS 67905   |  |
| Contact Person: Mike Fink   | Phone Number: ( 620 ) 624 - 3569   |
| Permit Number (API No. if applicable): 15-081-21816-0000  | Lease Name & Well No.: Hawley "A" #1   |
| Type of Pit:  | Pit Location (QQQQ):   |
| Emergency Pit Burn Pit  | <u>E/2</u> - <u>NE</u> - <u>SE</u>   |
| Settling Pit  | Sec. 14 Twp. 30S R. 32 East  West  |
|   | Feet from North / 🗸 South Line of Section  |
|   | Feet from  |
|   | Haskell County   |
| Was an artificial liner used? ☐ Yes ✓ No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Coated with Bentonite and natural cuttings. |  |
| Coated with Bentonite and natural cuttings.   |  |
| Coated with Bentonite and natural cuttings.   | RECEIVED KANSAS CORPORATION COMMISSION   |
| Coated with Bentonite and natural cuttings.  Abandonment procedure of pit:  | RECEIVED KANSAS CORPORATION COMMISSION SEP 2 5 2008  |
|   | SEP 2 5 2008   |
| Abandonment procedure of pit:   | SEP 2 5 2008   |
| Abandonment procedure of pit:  Pushed and backfilled with original material, then covered   | WANSAS CORPORATION COMMISSION  SEP 2 5 2008  With manure.  |
| Abandonment procedure of pit: Pushed and backfilled with original material, then covered  | with manure.  SEP 2 5 2008  With manure.  OXY USA, Inc. (Co.),                                       |
| Abandonment procedure of pit:  Pushed and backfilled with original material, then covered  The undersigned hereby certifies that he / she is Kenny Andrews                            | with manure.  SEP 2.5. 2008  With manure.  OXY USA, Inc. (Co.),                                      |
| Abandonment procedure of pit:  Pushed and backfilled with original material, then covered  The undersigned hereby certifies that he / she is Kenny Andrews                            | with manure.  SEP 2.5. 2008  With manure.  OXY USA, Inc. (Co.),                                      |
| Abandonment procedure of pit:  Pushed and backfilled with original material, then covered  The undersigned hereby certifies that he / she is Kenny Andrews                            | with manure.  SEP 2 5 2008  With manure.  OXY USA, Inc. (Co.), best of his/her knowledge and belief. |
| Abandonment procedure of pit:  Pushed and backfilled with original material, then covered  The undersigned hereby certifies that he / she is  | with manure.  SEP 2 5 2008  With manure.  OXY USA, Inc. (Co.), best of his/her knowledge and belief. |