## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Woolsey Operating Company, LLC	License Number: 33168
Operator Address: 125 N. Market, Suite 1000, Wichita, KS 67202	
Contact Person: Carl W. Durr	Phone Number: ( 620 ) 886 - 5606 #27
Permit Number (API No. if applicable): 15-007-23193 0000	Lease Name & Well No.: Lieb! #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>E2 . SW . SW</u>
Settling Pit	Sec. 6 Twp. 33 R. 10 East
Workover Pit Haul-Off Pit	660' Feet from North / V South Line of Section
	1180' Feet from East / West Line of Section
	Barber County
Date of closure: 1/11/08  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Clays from mud systems provided the seal	
Clays from mud systems provided the sear	
Clays from mud systems provided the seal	RECEIVED KANSAS CORPORATION COMMISSIO
Clays from mud systems provided the seal	KANSAS CORPORATION COMMISSIO
Abandonment procedure of pit:	MAR 0 7 2008  CONSERVATION DIVISION
	MAR 0 7 2008
Abandonment procedure of pit:	MAR 0 7 2008  CONSERVATION DIVISION
Abandonment procedure of pit: Pull water off pit with water truck then back fill with back h	MAR 0 7 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back has been been been back fill with back has been back fill with back h	Oe.    Conservation Division Wichita, ks   For Woolsey Operating (Co.),
Abandonment procedure of pit: Pull water off pit with water truck then back fill with back h	Oe.    Conservation Division Wichita, ks   For Woolsey Operating (Co.),
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back has been been been back fill with back has been back fill with back h	Oe.    Conservation Division Wichita, ks   For Woolsey Operating (Co.),
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back has been been been back fill with back has been back fill with back h	MAR 0 7 2008  CONSERVATION DIVISION WICHITA, KS  Tor Woolsey Operating (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back has back fill with back fill with back fill with back has back fill with back fill	MAR 0 7 2008  CONSERVATION DIVISION WICHITA, KS  Tor Woolsey Operating (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent