KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission \	Woods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-205-26969-0000	Lease Name & Well No.: Fortner 14-9
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW SE SW
Settling Pit	Sec. 9 Twp. 30 R. 14
Workover Pit Haul-Off Pit	876 Feet from North / 🗸 South Line of Section
	1808 Feet from East / West Line of Section
	Wilson
Date of closure: March 13, 2008	
Was an artificial liner used? Yes V No	
If no, how were the sides and bottom sealed to prevent downward migration of the Self-Sealing Pit	, pri comonic.
Jen-Jeaning Fit	RECEIVED KANSAS CORPORATION COMMISSIO
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
	MAR 2 7 2008
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	MAR 2 7 2008 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	MAR 2 7 2008 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the ACTARY NOTARY Authorized and sworn to me on this Authorized day of	MAR 2 7 2008 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Milds Jaylov Signature of Applicant or Agent
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	MAR 2 7 2008 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Milds Jaylov Signature of Applicant or Agent