## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Miss	ion Woods, KS 66205
Contact Person: Kimberlee Dixon	Phone Number: ( 620 ) 627 - 2499
Permit Number (API No. if applicable): 15-019-26874-0000	Lease Name & Well No.: Davidson 4-22
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW NW .
Settling Pit	Sec. 22 Twp. 32 R. 13 ✓ East West
Workover Pit Haul-Off Pit	660 Feet from North / South Line of Section
	660 Feet from East /  West Line of Section
	Chautauqua County
Was an artificial liner used?	
Was an artificial liner used? Yes Yes No  If no, how were the sides and bottom sealed to prevent downward migration  Self-Sealing Pit	of the pit contents?
If no, how were the sides and bottom sealed to prevent downward migration Self-Sealing Pit	RECEIVED
If no, how were the sides and bottom sealed to prevent downward migration Self-Sealing Pit  Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSIO
If no, how were the sides and bottom sealed to prevent downward migration Self-Sealing Pit	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 7 2008
If no, how were the sides and bottom sealed to prevent downward migration Self-Sealing Pit  Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSI
If no, how were the sides and bottom sealed to prevent downward migration Self-Sealing Pit  Abandonment procedure of pit:	RECEIVED  KANSAS CORPORATION COMMISSION  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED  KANSAS CORPORATION COMMISSION  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED  KANSAS CORPORATION COMMISSI  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), at to the best of his /her knowledge and belief.
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSI  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), at to the best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSI  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), at to the best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let evaporate until dry, then backfilled and restored.  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct NOTARY  PUBLIC  PUBLIC  My Appt. Exp.	RECEIVED KANSAS CORPORATION COMMISS  MAR 2 7 2008  CONSERVATION DIVISION WICHITA, KS  for Layne Energy Operating, LLC (Co.), at to the best of his /her knowledge and belief.  Signature of Applicant or Agent  day of