KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4
April 2004
Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Tengasco, Inc.	License Number: 32278
Operator Address: PO Box 458 Hays, KS 67601	
Contact Person: Gary Wagner	Phone Number: (785) 625 - 6374
Permit Number (API No. if applicable): 15-195-22500-00-00	Lease Name & Well No.: Howard #2
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW NE SW SE
Settling Pit ✓ Drilling Pit	Sec. 8 Twp. 15S R. 25 ☐ East
. Workover Pit Haul-Off Pit	1218' Feet from North / ✓ South Line of Section
ا المنظم الم المنظم المنظم المنظ	Trego County
	<u>.</u>
Date of closure: 3-14-08	
Was an artificial liner used? ☐ Yes ✓ No	
If we have seen the older and hadden applied to see and decreased discountry of the	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
If no, how were the sides and bottom sealed to prevent downward migration of the Native mud	pit contents?
· · · · · · · · · · · · · · · · · · ·	RECEIVED
· · · · · · · · · · · · · · · · · · ·	RECEIVED KANSAS CORPORATION COMMISSIO
Native mud	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 4 2008
Native mud Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSIO
Native mud Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMISSION MAR 2 4 2008 CONSERVATION DIVISION
Native mud Abandonment procedure of pit: Pits dried and backfilled to original contour.	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is Production Manage.	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Pits dried and backfilled to original contour.	RECEIVED KANSAS CORPORATION COMMISSION MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is Production Manager	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is Production Manages a duly authorized agent, that all information shown hereon is true and correct to the	RECEIVED KANSAS CORPORATION COMMISSION MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), the best of his /her knowledge and belief. May May Way May Signature of Applicant or Agent
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is Production Manager a duly authorized agent, that all information shown hereon is true and correct to the Subscribed and sworn to me on this day of	RECEIVED KANSAS CORPORATION COMMISSION MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSIO MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), the best of his /her knowledge and belief. May May Walled Co.
Abandonment procedure of pit: Pits dried and backfilled to original contour. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISSION MAR 2 4 2008 CONSERVATION DIVISION WICHITA, KS Tengasco, Inc. (Co.), the best of his /her knowledge and belief. May