Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Kansas Natural Gas Operating, Inc.	License Number: 32787
	32101
Operator Address: P O Box 815 Sublette, KS 67877	
Contact Person: Steve Lehning	Phone Number: (620) 675 - 8185
Permit Number (API No. if applicable): 15-055-21951-0000	Lease Name & Well No.: Hamlin 7-3
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SW _ NE _ NW _ 1/4
Settling Pit	Sec. 06 Twp. 25 R. 34 East West
☐ Workover Pit ☐ Haul-Off Pit	1290' Feet from 🗸 North / 🗌 South Line of Section
(Small On-Site Pit)	1420' Feet from East / West Line of Section
(6	Finney County
If no, how were the sides and hottom sealed to prevent downward migration of the	nit contents?
If no, how were the sides and bottom sealed to prevent downward migration of the Fresh water and drilling mud. Evaporate till dry and back	
Fresh water and drilling mud. Evaporate till dry and back	RECEIVED KANSAS CORPORATION COMMISS
Fresh water and drilling mud. Evaporate till dry and back	RECEIVED KANSAS CORPORATION COMMISSINDEC 2 6 2007
Fresh water and drilling mud. Evaporate till dry and back	RECEIVED KANSAS CORPORATION COMMISS
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. The undersigned hereby certifies that he / she is Supt.	RECEIVED KANSAS CORPORATION COMMISS DEC 2 6 2007 CONSERVATION DIVISION WICHITA, KS for Kansas Natural Gas Operating, Inc. (Co.),
Abandonment procedure of pit: Evaporate till dry. Backfill to complete.	RECEIVED KANSAS CORPORATION COMMISS DEC 2 6 2007 CONSERVATION DIVISION WICHITA, KS for Kansas Natural Gas Operating, Inc. (Co.),
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISS DEC 2 6 2007 CONSERVATION DIVISION WICHITA, KS for Kansas Natural Gas Operating, Inc. (Co.), se best of his /her knowledge and belief.
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMISS DEC 2 6 2007 CONSERVATION DIVISION WICHITA, KS for Kansas Natural Gas Operating, Inc. (Co.),
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMIS DEC 2 6 2007 CONSERVATION DIVISION WICHTA, KS for Kansas Natural Gas Operating, Inc. (Co.), se best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Evaporate till dry. Backfill to complete. The undersigned hereby certifies that he / she is	RECEIVED KANSAS CORPORATION COMMIS DEC 2 6 2007 CONSERVATION DIVISION WICHTA, KS for Kansas Natural Gas Operating, Inc. (Co.), se best of his /her knowledge and belief. Signature of Applicant or Agent