STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

RECEIVED
STATE GORPORATION COMMISSION

CONSERVATION

Jewel M. Ogden, Director 500 Insurance Building

212 North Market Wichita 2, Kansas
File No. County: Elles 17
Location: Nw-Sw-Sw Sec. 30 Twp. // Rge. LE (E) (W)
Name of Field:Total Depth: 3660
I have this date completed supervision of plugging of:
Lease Name: Tearry Well No. 3
Operator's Full Name: Malter Ally Co. Complete Address: 501 Corpheum By Wishite Kans.
Plugging Contractor: We Pipe Pufling
Address: Sheat Bend How. License No. 2
Oil Well D & A
Other well as hereafter indicated:
Was any delay in plugging operations caused by Conservation Division Agent? YesNo
If yes how long?Reason:
Operation Completed: Hour 6 pm Day 17 Month Cuy Year 1959
The above well was plugged as follows:
1. P. 3660 - P.Bt 3626 - 52 - 3659 - 8 1/8 - 175-
Dakote Hale slugged 698 with 250 sax coment.
Send to 3300 and topped with four suf coment.
Shat pipe at 467 and pulled to 447' conected sugar truck
and circulated much to cellar, then pumped so say dement
thru 5 2 Appe. Pulled 5 2 up to 170 and sungel so sax cement
thou 5's Agre. Pulled pipe out of hale, but 10' rack bridge,
at 45 and topped some with 10 say coment. Omentypy by Sun Cament,
Signed: Lilbert P. Leike
Conservation Division Agent
Reviewed: V. All CR

Field Supervisor

Remarks:

PLUGGING FILE SEC. 30 T// R/7W BOOK PAGE 62 LINE 30