## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Woolsey Operating Company, LLC	License Number: 33168
Operator Address: 125 N. Market, Suite 1000, Wichita, KS 67202	
Contact Person: Carl W. Durr	Phone Number: ( 620 ) 886 - 5606 Ext. 27
Permit Number (API No. if applicable): 15-095-22112 0000	Lease Name & Well No.: Schlichau No. 1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>SE . NW . SE . SE</u>
Settling Pit ✓ Drilling Pit	Sec. 24 Twp. 29 R. 6 East  West
Workover Pit Haul-Off Pit	900' Feet from North / 🗸 South Line of Section
	800' Feet from ✓ East / West Line of Section
	Kingman County
Date of closure: 11/27/07  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Clays from mud systems provided the seal	
o any o manufacture promise and obtain	
	RECEIVED KANSAS CORPORATION COMMISSION SEP 1 6 2008
Abandonment procedure of pit: Pull water off pit with water truck then back fill with back h	SEP 1 6 2008  CONSERVATION DIVISION
Abandonment procedure of pit:	SEP 16 2008
Abandonment procedure of pit:	SEP 1 6 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Pull water off pit with water truck then back fill with back h	SEP 1 6 2008  CONSERVATION DIVISION WICHITA, KS  forWoolsey Operating(Co.),
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back h  The undersigned hereby certifies that he / she is Field Manager	SEP 1 6 2008  CONSERVATION DIVISION WICHITA, KS  forWoolsey Operating(Co.),
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back h  The undersigned hereby certifies that he / she is Field Manager	SEP 1 6 2008  CONSERVATION DIVISION WICHITA, KS  forWoolsey Operating(Co.),
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back h  The undersigned hereby certifies that he / she is Field Manager	SEP 1 6 2008  CONSERVATION DIVISION WICHITA, KS  To Woolsey Operating (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Pull water off pit with water truck then back fill with back has back fill with back fill with back has back fill with back fill with back has back fill with bac	SEP 1 6 2008  OE CONSERVATION DIVISION WICHITA, KS  To Woolsey Operating (Co.), best of his /her knowledge and belief.  Signature of Applicant or Agent  April , 2008