## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: COLT ENERGY, INC	License Number: 5150
Operator Address: P O BOX 388, IOLA, KS 66749	
Contact Person: DENNIS KERSHNER	Phone Number: ( 620 ) 365 - 3111
Permit Number (API No. if applicable): 15-031-22,302 000	Lease Name & Well No.: BEARD 1-I
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NE . NE . NE . NE . </u>
Settling Pit	Sec. 11 _Twp. 23 _R. 16 East West
Workover Pit Haul-Off Pit	235 Feet from 🗸 North / 🗌 South Line of Section
	50 Feet from 🗸 East / West Line of Section
	<u>COFFEY</u> County
Date of closure: 4/22/08  Was an artificial liner used? ☐ Yes ✓ No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  POND HAD CLAY SIDES AND BOTTOM	
TOTAL TIME CENT CIDEO NIND BOTTOM	
TOND TIAD CEAT CIDEO AND DOTTON	RECEIVED KANSAS CORPORATION COMMISSION
	RECEIVED KANSAS CORPORATION COMMISSION MAY 0 2 2008
Abandonment procedure of pit:  PUMPED FLUID OUT - PUSHED PIT IN	MAY 0 2 2008  CONSERVATION DIVISION
Abandonment procedure of pit:	MAY 0 2 2008
Abandonment procedure of pit:	MAY 0 2 2008  CONSERVATION DIVISION
Abandonment procedure of pit: PUMPED FLUID OUT - PUSHED PIT IN	MAY 0 2 2008  CONSERVATION DIVISION WICHITA, KS  forCOLT ENERGY, INC(Co.),
Abandonment procedure of pit:  PUMPED FLUID OUT - PUSHED PIT IN  The undersigned hereby certifies that he / she is  a duly authorized agent, that all information shown hereon is true and correct to the SHIRLEY A STOTLER	MAY 0 2 2008  CONSERVATION DIVISION WICHITA, KS  forCOLT ENERGY, INC(Co.),
Abandonment procedure of pit:  PUMPED FLUID OUT - PUSHED PIT IN  The undersigned hereby certifies that he / she is	MAY 0 2 2008  CONSERVATION DIVISION WICHITA, KS  forCOLT ENERGY, INC(Co.), be best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  PUMPED FLUID OUT - PUSHED PIT IN  The undersigned hereby certifies that he / she is  a duly authorized agent, that all information shown hereon is true and correct to the SHIRLEY A STOTLER	MAY 0 2 2008  CONSERVATION DIVISION WICHITA, KS  forCOLT ENERGY, INC(Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit:  PUMPED FLUID OUT - PUSHED PIT IN  The undersigned hereby certifies that he / she is	MAY 0 2 2008  CONSERVATION DIVISION WICHITA, KS  forCOLT ENERGY, INC(Co.), be best of his /her knowledge and belief.  Signature of Applicant or Agent