## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Hemi Energy Group, Inc.	License Number: 33740
	1
Operator Address: 131 East Exchange Ave., Suite 223, Ft. Worth, TX	
Contact Person: Craig L. Treiber	Phone Number: ( 918 ) 607 - 8505
Permit Number (API No. if applicable): 15-207-27364-0000	Lease Name & Well No.: Collins Hemi #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	NW NE NE NE
☐ Settling Pit ✓ Drilling Pit	Sec. 30 Twp. 25 R. 17 ✓ East ☐ West
Workover Pit Haul-Off Pit	265 Feet from North / South Line of Section
	441 Feet from 📝 East / West Line of Section
	Woodson
	County
Date of closure: 11/5/2008	
Date of closure.	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Mud drilling pit	
маа алипу рк	RECEIVED KANSAS CORPORATION GÖMMISSI DA
миа атшпу рк	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	NOV 1 2 2008
	NOV 1 2 2008  CONSERVATION DIVISION:
Abandonment procedure of pit:	NOV 1 2 2008
Abandonment procedure of pit:	NOV 1 2 2008  CONSERVATION DIVISION:
Abandonment procedure of pit:	NOV 1 2 2008  CONSERVATION DIVISION:
Abandonment procedure of pit:	NOV 1 2 2008  CONSERVATION DIVISION:
Abandonment procedure of pit: Bulldoze in removed dirt. Blade smooth to ground level.	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Hepair Energy Group, Inc. (Co.),
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Hepair Energy Group, Inc. (Co.),
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Heprit Energy Group, Inc. (Co.), e best of his her knowledge and belief.
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Hepair Energy Group, Inc. (Co.),
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Heprit Energy Group, Inc. (Co.), e best of his her knowledge and belief.
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Heprit Energy Group, Inc. (Co.), e best of his her knowledge and belief.
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	NOV 1 2 2008  NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Hepritanergy Group, Inc. (Co.), the best of his Aper knowledge and belief.  Signature of Applicant or Agent  Author  Signature of Applicant or Agent
Abandonment procedure of pit:  Bulldoze in removed dirt. Blade smooth to ground level.  The undersigned hereby certifies that he / she is	NOV 1 2 2008  CONSERVATION DIVISION WICHITA, KS  for Heprit Energy Group, Inc. (Co.), e best of his her knowledge and belief.