CLOSURE OF SURFACE PIT

Operator Name: TDI, Inc.	License Number: 4787
Operator Address: 1310 Bison Road, Hays, Kansas 67601	
Contact Person: Tom Denning	Phone Number: (785) 628 - 2593
Permit Number (API No. if applicable): 15-051-25767-00-00	Lease Name & Well No.: Moore Farm #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE SW NW NW
☐ Settling Pit ✓ Drilling Pit	Sec. 4Twp. 15S _ R. 19 East
Workover Pit Haul-Off Pit	1260 Feet from V North / South Line of Section
	400 Feet from ☐ East / ✓ West Line of Section
	Ellis County
Date of closure: 9/02/08 Was an artificial liner used? Yes No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Pit was lined with native clay. Vent holes were knocked in on side of dike to help in evaporation.	
And the second of the second o	RECEIVED KANSAS CORPORATION COMMISSIO
Abandonment procedure of pit: Let pit dry. Push in clay soils first and then top soil. Level pit and restore location. NOV 0 3 2008	
——————————————————————————————————————	CONSERVATION DIVISION
	WICHITA, KS
The undersigned hereby certifies that he / she is president	for(Co.),
a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.	
<u> </u>	
211	Signature of Applicant or Agent
Subscribed and sworn to me on this day of	October 2008
HOWARD R. SLOAN Notary Public - State of Kansas	1
Trotaly I dollar Jointon I Trained	-1 Re
My Appt. Expires 8/29/12 My Commission Expires: 29 Acc 20	-1 Re