


**KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
CLOSURE OF SURFACE PIT**

Form CDP-4
April 2004
Form must be Typed

Operator Name: Noble Energy, Inc.	License Number: 33190
Operator Address: 1625 Broadway, Suite 2200, Denver, CO 80202	
Contact Person: Jennifer Barnett	Phone Number: (303) 228 - 4235
Permit Number (API No. if applicable): 15-023-20773-0000	Lease Name & Well No.: Rueb Farm 42-16
Type of Pit: <input type="checkbox"/> Emergency Pit <input type="checkbox"/> Burn Pit <input type="checkbox"/> Settling Pit <input checked="" type="checkbox"/> Drilling Pit <input type="checkbox"/> Workover Pit <input type="checkbox"/> Haul-Off Pit	Pit Location (QQQQ): SE - NE Sec. <u>16</u> Twp. <u>3S</u> R. <u>42</u> <input type="checkbox"/> East <input checked="" type="checkbox"/> West 1980' Feet from <input checked="" type="checkbox"/> North / <input type="checkbox"/> South Line of Section 660' Feet from <input checked="" type="checkbox"/> East / <input type="checkbox"/> West Line of Section <u>Cheyenne</u> County
Date of closure: <u>8/08/2007</u>	
Was an artificial liner used? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Sealed with clay soil, native and fresh mud.	
Abandonment procedure of pit: Drill cuttings are stirred with a trac-hoe, allow liquids to evaporate, let cuttings dry, and backfill.	
The undersigned hereby certifies that he / she is <u>Permit Representative</u> for <u>Noble Energy, Inc.</u> (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his /her knowledge and belief.	
	_____ Signature of Applicant or Agent _____ Subscribed and sworn to me on this <u>25th</u> day of <u>June</u> , <u>08</u> _____ Notary Public My Commission Expires: <u>My Commission Expires Aug. 20, 2008</u>

RECEIVED
KANSAS CORPORATION COMMISSION
JUN 26 2008
CONSERVATION DIVISION
WICHITA, KS