## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Midwestern Exploration Co.	License Number: 5263
Operator Address: 3500 S. Blvd, Suite 2B, Edmond, Oklahoma 73013	
Contact Person: Dale J. Lollar, President	Phone Number: ( 405 ) 340 - 4300
Permit Number (API No. if applicable): 15–189–22633–0000	Lease Name & Well No.: Streeter 1-15
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NE/4</u> _NW/4_
Settling Pit X Drilling Pit	Sec. 15 Twp. 35 R. 35 East X West
Workover Pit Haul-Off Pit	660 Feet from X North / South Line of Section
	1980 Feet from East / West Line of Section
	Stevens County
Date of closure:	
Was an artificial liner used? Yes X No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  RECEIVED	
Pit is self-sealing with drilling mud.	KANSAS CORPORATION COMMISSIO
8	
	JUL 2 1 2008
	JUL 2 1 2008  CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	CONSERVATION DIVISION
	CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:	CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,	conservation division Wichita, Ks side walls pushed in and leveled.  for Midwestern Exploration Co (Co.),
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,  The undersigned hereby certifies that he / she is	conservation division wichita, ks  side walls pushed in and leveled.  for Midwestern Exploration Co (Co.).  be best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,  The undersigned hereby certifies that he / she is President a duly authorized agent, that all information shown hereon is true and correct to the	conservation division Wichita, Ks  side walls pushed in and leveled.  for Midwestern Exploration Co (Co.),  be best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,  The undersigned hereby certifies that he / she is	conservation division wichita, ks  side walls pushed in and leveled.  for Midwestern Exploration Co (Co.).  be best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	conservation division with the side walls pushed in and leveled.  for Midwestern Exploration Co (Co.), expect of his /her knowledge and belief.  Signature of Applicant or Agent  July , 2008
Abandonment procedure of pit:  Evaporation to atmosphere until completely dry,  The undersigned hereby certifies that he / she is a duly authorized agent, that all information shown hereon is true and correct to the	conservation division witchita, ks  side walls pushed in and leveled.  for Midwestern Exploration Co (Co.), expect of his /her knowledge and belief.  Signature of Applicant or Agent  July , 2008  Notary Public ANITA DUNN