KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Layne Energy Operating, LLC	License Number: 33365
Operator Address: 1900 Shawnee Mission Parkway, Mission Woods, KS 66205	
Contact Person: Kimberlee Dixon	Phone Number: (620) 627 - 2499
Permit Number (API No. if applicable): 15-125-31330-0000	Lease Name & Well No.: McMillin 7-10
Type of Pit: Emergency Pit Burn Pit	Pit Location (QQQQ):
Settling Pit	SW _ NE Sec. 10 _ Twp. 33 _ R. 16
Workover Pit	
Workover Fit	Feet from North / South Line of Section
	Feet from Fast / West Line of Section Montgomery
	County
Date of closure: November 16, 2007	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Self-Sealing Pit	RECEIVED KANSAS CORPORATION COMMISSION
Self-Sealing Pit Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
	DEC 1 4 2007
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	DEC 1 4 2007 CONSERVATION DIVISION
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored.	DEC 1 4 2007 CONSERVATION DIVISION WICHITA, KS
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Huke Saylor
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS Layne Energy Operating, LLC (Co.),
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Huke Saylor
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Huke Saylor
Abandonment procedure of pit: Let evaporate until dry, then backfilled and restored. The undersigned hereby certifies that he / she is	DEC 14 2007 CONSERVATION DIVISION WICHITA, KS for Layne Energy Operating, LLC (Co.), e best of his /her knowledge and belief. Huke Saylor