

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Vess Oil Corporation
Address: 1700 N. Waterfront Pkwy #500 Wichita, Kansas 67206
Phone: (316) 682-1537 Operator License #: 5030
Type of Well: Oil Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: _____ (Date)
by: Mike Meyers (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-083-10340-0000
Lease Name: EF Lippoldt EF-B
Well Number: B-3 KCCPKTPEI CP213
Spot Location (QQQQ): _____ - _____ - NW - NW
660 Feet from North / South Section Line
660 Feet from East / West Section Line
Sec. 13 Twp. 23 S. R. 23 East West
County: Hodgeman
Date Well Completed: ~~1984~~
Plugging Commenced: 2-3-09
Plugging Completed: 2-5-09

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
				8-5/9"	253'	None
				4-1/2"	4540'	None

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Plugged off bottom with sand to 4400' and 4 sxs. cement. Perforated casing @450', ran tubing to 1200'. pumped 150 sxs. cement, lost circulation.
Pulled 2 jts. of tubing, pumped 35 sxs. cement, no circulation. Let well set, checked hole to 1500', no cement. Ran tubing back to 1260', pumped 60 sxs., lost circulation. Let set overnight, cement @1571', Ran in 1200' of tubing, pumped 3 sxs. gel & 100 sxs. to surface.
Topped off w/10 sxs. Pumped 100 sxs. down 8-5/8" surface. Plugging Complete.

KANSAS CORPORATION COMMISSION

Name of Plugging Contractor: Mike's Testing & Salvage, Inc. License #: 31529
Address: P.O. Box 467 Chase, Kansas 67524

**FEB 25 2009
RECEIVED**

Name of Party Responsible for Plugging Fees: Vess Oil Corporation
State of Kansas County, Rice, ss.


Mike Kelso (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts stated herein, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Signature) Mike Kelso

(Address) P.O. Box 467 Chase, Kansas 67524

SUBSCRIBED and SWORN TO before me this 20th day of February, 2009

Irene Herzberg My Commission Expires: _____
Notary Public



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

PKT