KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: JayHawk Energy, Inc.	License Number: 34102
Operator Address: P.O. Box 191, Girard, Kansas 66743	
Contact Person: Tony Anderson	Phone Number: (620) 724 - 7040
Permit Number (API No. if applicable): 15-037-22060-0000	Lease Name & Well No.: Dean Davied #11-6
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>W/2</u> <u>W/2</u> <u>SW</u>
☐ Settling Pit ✓ Drilling Pit	Sec. 11 _Twp. 28S _R. 23 _ ✓ East ☐ West
Workover Pit Haul-Off Pit	1330' Feet from North / South Line of Section
	330' Feet from East / ✓ West Line of Section
	<u>Crawford</u> County
Date of closure: 12-2-08 Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
RECEIVED Sealed by native clays KANSAS CORPORATION COMMISSION	
Gedied by Halive Clays	KANSAS CORPORATION COMMISSION
Gealed by Halive days	DEC 1 1 2008
Sealed by Halive days	DEC 1 1 2008 CONSERVATION DIVISION
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to i	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS collecting and disposing in a SWD well the
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to i	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS collecting and disposing in a SWD well the ts natural condition.
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to i	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS collecting and disposing in a SWD well the ts natural condition.
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to i	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS collecting and disposing in a SWD well the ts natural condition.
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to interest the undersigned hereby certifies that he / she is	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS collecting and disposing in a SWD well the ts natural condition. Example 1 2008 COL), when the second in
Abandonment procedure of pit: Pit was backfilled after dry thru natural evaporation and corresidual fluid. The area was then graded and restored to it. The undersigned hereby certifies that he / she is the General Manage a duly authorized agent, that all information shown hereon is true and correct to the Augustian.	DEC 1 1 2008 CONSERVATION DIVISION WICHITA, KS Collecting and disposing in a SWD well the ts natural condition. Example 1 2008 Conservation division with the the service of the servi