Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Lario Oil & Gas Co.	License Number: 5214
Operator Address: 301 S. Market St. Wichita,	KS 67202
Contact Person: Jay G. Schweikert	Phone Number: (316) 265 - 5611
Permit Number (API No. if applicable): 15-051-25500 © 000	Lease Name & Well No.: Marshall E #27
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u></u> _ <u>SW</u>
Settling Pit ✓ Drilling Pit	Sec. 24 Twp. 11 R. 18 East West
Workover Pit Haul-Off Pit	1730 Feet from North / ✓ South Line of Section
	2190 Feet from ☐ East / ✓ West Line of Section
	Ellis County
Was an artificial liner used? Yes No If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Bentonite in mud.	
Bentonite in mud.	
Bentonite in mua.	RECEIVED KANSAS CORPORATION COMMISSIO
Abandonment procedure of pit:	
	mar 0 4 2008 n and leveled off. conservation division
Abandonment procedure of pit:	MAR 0 4 2008
Abandonment procedure of pit:	MAR 0 4 2008 n and leveled off. Conservation division Wichita, ks
Abandonment procedure of pit: Evaporate water holding in pit. Cut walls. Pits filled in	MAR 0 4 2008 n and leveled off. Conservation division Wichita, ks Engineer for Lario Oil & Gas Company (Co.),
Abandonment procedure of pit: Evaporate water holding in pit. Cut walls. Pits filled in the superior of pits. The undersigned hereby certifies that he / she is an Operations Expression of the superior of pits.	MAR 0 4 2008 n and leveled off. Conservation division Wichita, ks Engineer for Lario Oil & Gas Company (Co.),
Abandonment procedure of pit: Evaporate water holding in pit. Cut walls. Pits filled in the superior of pits. The undersigned hereby certifies that he / she is an Operations Expression of pits.	MAR 0 4 2008 n and leveled off. Conservation division wichita, ks Engineer for Lario Oil & Gas Company (Co.),
Abandonment procedure of pit: Evaporate water holding in pit. Cut walls. Pits filled in the second of the second	MAR 0 4 2008 In and leveled off. Conservation division Wichita, ks Engineer for Lario Oil & Gas Company (Co.), to the best of his /her knowledge and belief.
Abandonment procedure of pit: Evaporate water holding in pit. Cut walls. Pits filled in the content of the con	MAR 0 4 2008 In and leveled off. CONSERVATION DIVISION WICHITA, KS Engineer for Lario Oil & Gas Company (Co.), to the best of his /her knowledge and belief. Signature of Applicant or Agent