## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: R & B Oil & Gas, Inc.	License Number: 31191
Operator Address: PO Box 195, Attica, KS 67009	
Contact Person: Randy Newberry	Phone Number: ( 620 ) 254 - 7251
Permit Number (API No. if applicable): 15-007-23069-00-01	Lease Name & Well No.: Hunter-Gramley A1 OWWO
Type of Pit:	
	Pit Location (QQQQ): SW NE SE SE
Emergency Pit Burn Pit	
Settling Pit ✓ Drilling Pit	Sec. 36 Twp. 32S R. 11 ☐ East  West
Workover Pit Haul-Off Pit	Peet from North / J South Line of Section
	Feet from V East / West Line of Section
	County
Date of closure: 4-7-08	
Was an artificial liner used? ☐ Yes ✔ No	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Drilling Mud	
Diming Mad	†
Drining Wide	
Drining Wide	RECEIVED
	RECEIVED KANSAS CORPORATION COMMIS <b>SIO</b> N
Abandonment procedure of pit:	RECEIVED KANSAS CORPORATION COMMIS <b>SION</b> APR 14 2008
	KANSAS CORPORATION COMMISSION  APR 1 4 2008  CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION APR 14 2008
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION  APR 1 4 2008  CONSERVATION DIVISION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION  APR 1 4 2008  CONSERVATION DIVISION
Abandonment procedure of pit:  Let dry, push shut	KANSAS CORPORATION COMMISSION  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc(Co.),
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is Sec./Treas	KANSAS CORPORATION COMMISSION  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc(Co.),
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is Sec./Treas  a duly authorized agent, that all information shown hereon is true and correct to the	APR 1 4 2008  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is Sec./Treas	APR 1 4 2008  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is Sec./Treas  a duly authorized agent, that all information shown hereon is true and correct to the	APR 1 4 2008  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is	APR 1 4 2008  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  To R & B Oil & Gas, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  April 2008
Abandonment procedure of pit:  Let dry, push shut  The undersigned hereby certifies that he / she is	APR 1 4 2008  APR 1 4 2008  CONSERVATION DIVISION WICHITA, KS  for R & B Oil & Gas, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent