## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: BlueRidge Petroleum Corporation	License Number: 31930
Operator Address: P.O. Box 1913 Enid, OK 73702	
Contact Person: Jonathan Allen	Phone Number: ( 580 ) 242 - 3732
Permit Number (API No. if applicable): 15-135-24807-0000	Lease Name & Well No.: Antenen #1-36
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>SESWSW</u>
Settling Pit	Sec. 36 Twp. 18S R. 26 East  West
Workover Pit Haul-Off Pit	415 Feet from North / South Line of Section
	919 Feet from East / West Line of Section
	County
Date of closure:2/03/2009	
Date of closure.	
Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the	pit contents?
Native and fresh mud	
Native and fresh mud	KANSAS CORPORATION COMMISSION
Native and fresh mud	KANSAS CORPORATION COMMISSION
Native and fresh mud  Abandonment procedure of pit:	MAR 0 2 2009
Abandonment procedure of pit:	MAR 0 2 2009
Abandonment procedure of pit:	MAR 0 2 2009
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.	MAR 0 2 2009 RECEIVED
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.	MAR 0 2 2009 RECEIVED  for BlueRidge Petroleum Corporation (Co.),
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is President	MAR 0 2 2009 RECEIVED  for BlueRidge Petroleum Corporation (Co.),
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is President	MAR 0 2 2009 RECEIVED  for BlueRidge Petroleum Corporation (Co.),
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is President	MAR 0 2 2009  RECEIVED  for BlueRidge Petroleum Corporation (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is President a duly authorized agent, that all information shown hereon is true and correct to the	MAR 0 2 2009  RECEIVED  for BlueRidge Petroleum Corporation (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is	MAR 0 2 2009  RECEIVED  for BlueRidge Petroleum Corporation (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  February 2009
Abandonment procedure of pit:  Allow liquid contents to evaporate then backfill.  The undersigned hereby certifies that he / she is President a duly authorized agent, that all information shown hereon is true and correct to the  Subscribed and sworn to me on this CURT GO Notal  Output  Description:  Output  Descr	MAR 0 2 2009  RECEIVED  for BlueRidge Petroleum Corporation (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  February 2009  ILBERTSON Public of Oklahoma