## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Bobcat Oilfield Services, Inc.	License Number: 3895
Operator Address: 30805 Cold Water Rd. Louisburg, KS. 66053	
Contact Person: Bob Eberhart	Phone Number: ( 913 ) 837 - 2823
Permit Number (API No. if applicable): 15-107-23948-00-00	Lease Name & Well No.: Synder W-21N
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE NE SE NE
Settling Pit	Sec. 8 Twp. 20 R. 23 ✓ East ☐ West
Workover Pit Haul-Off Pit	3590 Feet from North / ✓ South Line of Section
	330 Feet from 🗹 East / West Line of Section
•	<u>Linn</u> County
Date of closure: 11/18/08  Was an artificial liner used? ☐ Yes ✓ No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Use drilling mud	
ooo ammig maa	
	KANSAS CORPORATION COMMISSION
Abandonment procedure of pit:	KANSAS CORPORATION COMMISSION
	FEB 2 3 2009
Abandonment procedure of pit:	
Abandonment procedure of pit:	FEB 2 3 2009
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that he / she isAgent	FEB 2 3 2009 RECEIVED  forBobcat Oilfield Services, Inc(Co.),
Abandonment procedure of pit:  Air dried and filled with dirt.	FEB 2 3 2009 RECEIVED  for Bobcat Oilfield Services, Inc. (Co.), the best of his /her knowledge and belief.
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that he / she is	FEB 2 3 2009 RECEIVED  forBobcat Oilfield Services, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that he / she is Agent a duly authorized agent, that all information shown hereon is true and correct to the	FEB 2 3 2009 RECEIVED  for Bobcat Oilfield Services, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that he / she is	FEB 2 3 2009 RECEIVED  forBobcat Oilfield Services, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that he / she is	FEB 2 3 2009  RECEIVED  for Bobcat Oilfield Services, Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent  February , 2009