## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Carmen Schmitt Inc.	License Number: 6569
Operator Address: P.O. Box 47, Great Bend, KS 67530	
Contact Person: Carmen Schmitt	Phone Number: ( 620 ) 793 - 5100
Permit Number (API No. if applicable): 109-20808-0000	Lease Name & Well No.: Brungardt #1
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NW _ SW _ NE</u>
Settling Pit	Sec. 22 Twp. 13 R. 34 East  West
Workover Pit Haul-Off Pit	1900 Feet from 📝 North / South Line of Section
	2310 Feet from 🗸 East / West Line of Section
	Logan County
Date of closure: 2-2-09  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Native clays and bentonite	
Native clays and bentonite	
Native clays and bentonite	RECEIVED
	RECEIVED MAR 1 3 2009
Abandonment procedure of pit:	MAR 1 3 2009
	2 2
Abandonment procedure of pit:  Evaporate and backfill	MAR 1 3 2009 KCC WICHITA
Abandonment procedure of pit:  Evaporate and backfill  The undersigned hereby certifies that he / she is Operations Manage	MAR 1 3 2009  KCC WICHTA  er for Carmen Schmitt Inc. (Co.),
Abandonment procedure of pit:  Evaporate and backfill  Operations Manage	MAR 1 3 2009  KCC WICHTA  er for Carmen Schmitt Inc. (Co.),
Abandonment procedure of pit:  Evaporate and backfill  The undersigned hereby certifies that he / she is Operations Manage	MAR 1 3 2009  KCC WICHITA  er for Carmen Schmitt Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit:  Evaporate and backfill  The undersigned hereby certifies that he / she is Operations Manage a duly authorized agent, that all information shown hereon is true and correct to the	ErforCarmen Schmitt Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Evaporate and backfill  The undersigned hereby certifies that he / she is Operations Manage	ErforCarmen Schmitt Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent
Abandonment procedure of pit:  Evaporate and backfill  The undersigned hereby certifies that he / she is Operations Manage a duly authorized agent, that all information shown hereon is true and correct to the Subscribed and sworn to me on this day of	ErforCarmen Schmitt Inc. (Co.), e best of his /her knowledge and belief.  Signature of Applicant or Agent