KANSAS CORPORATION COMMISSION CONSERVATION DIVISION 130 S. MARKET – ROOM 2078 WICHITA STATE OFFICE BUILDING WICHITA, KANSAS 67202

KANSAS CORPORATION COMMISSION

APR 0 6 2009

RECEIVED

CLOSURE OF SURFACE POND

OPERATOR NAME	LICENCE NO.
PETROSANTANDER (USA) INC	32198
OPERATOR ADDRESS RECEIVE	ED .
_6363 WOODWAY, #350, HOUSTON, TEXAS 77057 APR 2 3 2	2009
CONTACT PERSON KCC WICH	IITA PHONE NUMBER
LILIANA HERNANDEZ	(713) 784-8700
PERMIT NUMBER (API # if applicable) 15093-21817-0000	LEASE NAME
15-093/21877) 9/8/17 (soms - mis-legal)	UNRUH 3R
TYPE OF POND:	PIT LOCATION
Emergency Pit Burn pit	Sec <u>13</u> Twp <u>21</u> S Rng <u>35</u> E/W
Treatment Pit X Drilling Pit	460 Ft from N/S line of Sec (circle one)
Workover Pit	1980 Ft from E/W line of Sec (circle one)
	KEARNY County
D-4£ Classes March 14h 2000	
Date of Closure: March 14h, 2009	
Was an artificial liner used? Yes X No	
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Notice made and along.	•
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Notice made and along.	ne pit contents?
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays Abandonment procedure of pond:	
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays	
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays Abandonment procedure of pond:	
Was an artificial liner used? If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays Abandonment procedure of pond: Backfill and replace topsoil then level as close as possible to its natural state. The undersigned hereby certifies that he/she is for PETROSANTANDER (USA) INC (Co.), a duly authorized agent,	e
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays Abandonment procedure of pond: Backfill and replace topsoil then level as close as possible to its natural state. The undersigned hereby certifies that he/she is LILIANA HERNANDEZ	e
Was an artificial liner used? Yes X No If no, how were the sides and bottom sealed to prevent downward migration of the Native muds and clays Abandonment procedure of pond: Backfill and replace topsoil then level as close as possible to its natural state. The undersigned hereby certifies that he/she is for PETROSANTANDER (USA) INC (Co.), a duly authorized agent, correct to the best of their knowledge and belief	that all)information shown hereon is true and Solution of Texas spires