## KCC OIL/GAS REGULATORY OFFICES

Date: <u>09/26/08</u>	District: 02	Case #:
	New Situation	Lease Inspection
	Response to Request	Complaint
	<b>√</b> Follow-Up	Field Report
Operator License No: 33639	API Well Number: <u>15-015-23729-00-00</u>	
Op Name: CHARLES O ULLUM / ULLUM OIL CO.		Twp 27 S Rng 5 VE / W
Address 1: 9333 SE TURKEY CREEK RD		Feet from N/S Line of Section
Address 2:		Feet from FE/W Line of Section
City: LEON	GPS: Lat:Long: _	
State: KS. Zip Code: 67074 -9022		Well #: 24-02
Operator Phone #: (316) 745-3316	County: Butler	
Reason for Investigation:		
PIT EXTENSIONS		
Problem:		
	TO FILL DITE	
OPERATOR HAS REQUESTED MORE TIME	TO FILL PITS.	
Persons Contacted:		
NONE	·	
Findings:		
LOCATED WELL SITE, DRILLING PITS HAV	E BEEN CLOSED. WELL IS	PLUGGED.
		RECEIVED
		KANSAS CORPORATION COMMISSION
		OCT 0 6 2008
		CONSERVATION DIVISION
		WICHITA, KS
Action/Recommendations: Follow	Up Required Yes No	Date:
CC: SAMMY K. FLAHARTY		
UPDATE RBDMS		
	<del></del>	
Verification Sources:		Photos Taken: NO
RBDMS KGS T.	A Program	
	ourthouse By: DUANE KRI	JEGER
✓ Other: LEASE INSPECTION		5 Tang
Retain I Copy District Office		

Send 1 Copy to Conservation Division

Form: \_\_\_\_\_