

11-12 15-051-05009-0001

4-060462

E-03,145

API number: 15- - 5-21-50

TO: STATE CORPORATION COMMISSION  
CONSERVATION DIVISION - PLUGGING  
200 COLORADO DERBY BUILDING  
WICHITA, KANSAS 67202

NW SW NW /4 SEC. 01, 11 S, 16 W  
3630 feet from S section line  
4950 feet from E section line

(Formerly Bowlby B-1)

Operator license# 5447

Lease Krueger well #801W

Operator: OXY USA, Inc.

County Ellis

Address: Box D  
Plainville, Kansas 67663

Well total depth 3548 feet  
Conductor Pipe: 0 inch @ 0 feet  
Surface pipe 8 5/8 Inch @ 276 feet

115.31

Aband. oil well \_\_, Gas well \_\_, Input well X, SWD \_\_, D & A \_\_

Plugging contractor: Co Tools License#

Address:

Company to plug at: Hour: 2:30 P.M. Day: 12 Month: November Year: 93

Plugging proposal received from: Don Shelton

Company: OXY USA, Inc. Phone: 913-434-2350

Were: Order 300 sxs. 60/40 posmix - 10% gel and hulls.  
Squeezed at 690' with 217 sxs. cement.  
Fluid level 2000'.

Plugging Proposal Received by: Herb Deines  
Plugging operations attended by agent? All [ X ], Part [ ], None [ ]

Completed: Hour: 3:30 P.M., Day: 12, Month: November, Year: 93

Actual plugging report: 8 5/8" to 276'. 5 1/2" to 3458'. Perfs. at  
300' - 1220' - 1870'. Tied onto production casing and pumped 275 sxs.  
cement with 250# hulls. Max. 300. S.I.P. 50#. Tied onto annulus  
with instant 500# S.I.P.

RECEIVED  
STATE CORPORATION COMMISSION  
11-19-93  
NOV 19 1993

Remarks: Halliburton Cementing.  
Condition of casing(in hole): GOOD BAD X Anhy. plug: YES X NO  
Bottom plug(in place): YES, CALC X, NO Dakota plug: YES X, NO  
Plugged through TUBING, CASING X. Elevation: 1975 GL

CONSERVATION DIVISION  
Wichita, Kansas

I did [ X ] / did not [ ] observe the plugging.

DH (agent)

DATE NOV 22 1993

INV. NO. 39279