Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-5 August 2004 Form must be Typed

EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: Endeavor Energy Resources, LP	License Number: 32887
Operator Address: PO Box 40, Delaware, OK 74027	
Contact Person: Joe Driskill	Phone Number: (918) 467 - 3111
Permit Number (API No. if applicable): 15-099-24452-0000	Lease Name: Tate Ranch
Source of Waste: Dike Settling Pit Workover Pit Burn Pit Haul-off Pit Steel Pit Spill / Escape	Well Number: 7-1 Source Location (QQQQ): SW _ SW _ SW Sec. 7 _ Twp. 34 _ R. 18
Type of waste to be disposed: Fluid Soil Mud / Cuttings	Other:
Amount of waste: No. of loads Barrels	YDS
Destination of waste: Reserve Pit Disposal Well Lease Room	ad Dike / Berm Other:
If waste is transferred to another reserve pit, is the lease active?	lo
Location of waste disposal: Operator Name: Lease Name: Docket No.: Air Drilled~ No Fluids	
The undersigned herby certifies that he / she is Joe Driskill for Endeavor Energy Resources, LP (Co.), a duly audit and correct to the best of his / her knowledge and belief. Subscribed and sworn to before me on this 20th day of November	horized agent, that all information shown hereon is true Agent Signature 2008