Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-5 August 2004 Form must be Typed

EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-141-20,382 0000	Lease Name: Hobrock
Source of Waste: Dike Emergency Pit Settling Pit Workover Pit Burn Pit Haul-off Pit Steel Pit Spill / Escape Type of waste to be disposed:	Well Number: #1 Source Location (QQQQ): SE _ NE _ NW _ NW Sec. 20 _ Twp. 10S _ R. 15 _ East
Amount of waste: 7 No. of loads 560 total Barrels Tons YDS	
Destination of waste: ☐ Reserve Pit ☑ Disposal Well ☐ Lease Roa	ad Dike / Berm Other:
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal: Operator Name: John O. Farmer, Inc. Lease Name: Trapp "B" #2 Docket No.: D-28,844 Docket No.: D-28,844 County: Russell RECEIVED KANSAS CORPORATION COMMISSION WICHITA, KS	
The undersigned herby certifies that he / she is president for John O. Farmer, Inc. (Co.), a duly authorized agent, that all information shown hereon is true and correct to the best of his / her knowledge and belief. Subscribed and sworn to before me on this 16th day of June 2008 NOTARY PUBLIC - State of Kansas May Sept. Eas. 1-27-09 My Commission Expires	