KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-5 August 2004 Form must be Typed

EXPLORATION & PRODUCTION WASTETRANSFER

Operator Name: John O. Farmer, Inc.	License Number: 5135
Operator Address: P.O. Box 352, Russell, KS 67665	
Contact Person: Marge Schulte	Phone Number: (785) 483 - 3145, Ext. 214
Permit Number (API No. if applicable): 15-141-20,383 ტ りつつ	Lease Name: Hogan "A"
Source of Waste:	Well Number: #1
Dike □ Emergency Pit □ Settling Pit □ Workover Pit □ Drilling Pit □ Burn Pit □ Haul-off Pit □ Steel Pit □ Spill / Escape	Source Location (QQQQ): NE SE NE SW Sec. 16 Twp. 10S R. 15 East
Type of waste to be disposed:	Other:
Amount of waste: 8 No. of loads 640 total Barrels	YDS
Destination of waste: Reserve Pit Disposal Well Lease Roa	ad Dike / Berm Other:
If waste is transferred to another reserve pit, is the lease active? Yes No	
Location of waste disposal: Operator Name: John O. Farmer, Inc. Lease Name: Trapp "B" #2 Docket No.: D-28,844	Date of Waste Transfer: 2-22-08 License No.: 5135 Sec. 8 Twp. 12S R. 13 East West County: Russell RECEIVED ANSAS CORPORATION COMMISSION JUN 18 2008 CONSERVATION DIVISION MATCHITA, KS
The undersigned herby certifies that he / she is president for John O. Farmer, Inc. (Co.), a duly authorized and correct to the best of his / her knowledge and belief. Subscribed and sworn to before me on this 16th day of June MOTARY PUBLIC - State of Kansas MARGARET A SCHULTE My Appt. Eng. 1-27-09	Forized agent, that all information shown hereon is true Agent Signature Agent Quality Agent Quality And All information shown hereon is true Agent Signature Agent Signature