

Date 8/13/09

- New Situation
- Response to Request
- Follow-up

Operator license # 3842

Operator Larson Operating Co

Address 562 W State Road 4

Location SE NW NW SW, Sec 29, T 19 S, R 29 W

Olmitz, KS 67564-8561

Lease Johnson Farms Well # 1-29

Operator phone number 620 653-7368

County Lar

API # 15-101-22182-0000

Reason for Investigation: _____

Alternate II Cementing

Problem: _____ Co Man: Tom Larson

Person(s) Contacted: _____

Findings: 8 3/8" @ 264', 5 1/2" @ 4743' w/ 225sx; TD=4744';
Port Collar @ 2185';

Swift Services pumped 215sx SMD cement thru
port collar. Circ 15sx to the pit.

RECEIVED

AUG 31 2009

photos taken: KCC WICHITA

Action/Recommendations: Alt II Cementing Complete

- Lease Inspection
- Complaint
- Field Report

RECEIVED

AUG 24 2009

KCC DODGE CITY

By Ken Jehlke

PIR T II

Retain 1 copy Joint District Office
Send one copy Conservation Division

- RBDMS
- KGS
- District files
- TA program
- T-1 database
- Courthouse

