STATE OF KANSAS STATE CORPORATION COMMISSION

Form CP-4

Give All Information Completely	
Make Required Affidavit	
Mail or Deliver Report to:	
Conservation Division	
State Corporation Commiss	lon

WELL PLUGGING RECORD

State Corporation Commission P. O. Box 17027		Pooks		- 10 -	- 10					
Wichita, Kansas 67217	Location as "l	NE/CNWISWI"	Count or footage fro	y. Sec <u>. 18</u> 7 m lines 990-	Wp_LU Rge -N-Line 3	19 (E) W (W)				
	Location as "NE/CNW%SW%" or footage from lines 990-N-Line 330 -W-Line Lease Owner Russ Casing Pulling, Inc.									
	Lease Name _	Lesse Name Lillian Scoggins								
	Office Address	Office Address Box 1082 Great Bend, Kansas								
		Well (completed		• •						
	•	npleted								
		r plugging filed_								
						19				
		Plugging commenced 5-2-73 Plugging completed 5-15-73								
	Reason for abandonment of well or producing formation									
	1	Not Comme								
	If a producing	g well is abandon	ed, date of la	st production_		19				
Locate well correctly on above						ore plugging was com-				
Section Plat Name of Conservation Agent who supe	menced?	Ye	S Too Mad	CCAV						
Producing formation Kansas C	irvised plugging of the	Death to too 34	62 P-4-	- SSE Y	m-1-1-D-1-1-1	wall 3777 Fact				
Show depth and thickness of all water			Dotton		Total Depth of	Well 3/// Feet				
-	-	,us.								
OIL, CAS OR WATER RECORD)S			·		CASING RECORD				
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT				
				8 1/8	1635	None				
		ļ		5 1/2	3773	2690				
***************************************			ļ			 				
					· · · · · · · · · · · · · · · · · · ·					
Consideration of the second se						<u> </u>				
5-2-73 Plugge	ed off bottom	- Dumped s	and to 3	200	STATE CO	RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED RECEIVED				
Mixed	and dumped 5	-sacks-ceme	nt.	· · · · · · · · · · · · · · · · · · ·	6-26-7	3 COMMISS				
5-15-73 Plugg	ed off top.	Set 15' Roc	k Bridge	from 720'	Q _{ONSC}	ATION DIVISION				
+0.73	51 Dumped 3	vds. 3000#	P.S.T. 1	Ready Mix	Wind	4710N =				
		-y			<u></u>	ATION DIVISION				
Concre	ete to 500'.	Mudded cas	ing to			3,535				
2251.	Rock bridge	from 225	to 210'.							
3_yds	Ready Mix C	oncrete fro	m 210' to	o base of	cellar.					
-		 								
	(If additions	description is neces	anry, use BACK	of this sheet)						
Name of Plugging Contractor	Russ Casing	Pulling, In	C.							
Address Box 10	<u> </u>	t Bend, Kan	sas							
STATE OF <u>Kansas</u> <u>Russ Casing Pull</u>	, COU	JNTY OF			,					
well, being first duly sworn on oath, s	ays: That I have kn	rowledge of the f	acts, statemer	wher) or (owners,) and matter	er or operator) berein contain	of the above-described led and the log of the				
above described well as filed and that	THE SULL SIG CIUS &			1 11	Peran	5 .				
5 A		(Signature)	will		u on	/_/_				
4 4 M			SON 10	082	17. Joen.	Lus.				
SPRISCRIPED WAY SWORN TO before	e me this2!	5th day of		June	(ddress)	3.				
My commission expires 4-27-79			7	1200	19/)				
My commission expires 4-27-72				star 19	Kares	Notary Public.				
My commission expires 4-11-73					11	wotary rupiic.				

#5

SKELLY OIL COMPANY

			_			S	V_{Γ}	للبلاد	_ T	\cup	LL	<i>ـ ر</i>		TATA	L
			_							W	cll	Recor	d		/
		- -	4				.,		a		#	35956	5	c	2226 BH
	8	#35956 2226 EH Lease Name and No. Lillian Scoggins Well No. 5 Elev. 2231 DF													
	Lease Description SW/4 and N/2 SE/4 Section 18-10S-19W, Rooks County, Kansas														
			-												
.			-										J. C	ine SVI/4	
<u> </u>	UTH		ل											ine of Sac.	
Work com'dMay	•	1	0 5.												
Rig Contractor									rig. con	1'4	.2.1	. 	19 Dr	ig. comp a	_= <i>L</i>
Drilling Contractor									Tu'	1 90 .	0	klaho			
Rotary Drilling from		тто.	TIM		. 37	751	.www.y.	C1	.l. T.		<u></u>		37751	3'	7771
							Inicial	Cat	hafa-a :	ar Drill	ing	170m	101 OT	H 12 hour	rsBbls.
Commenced Produci	ng	June	22		19_4	9	Initial	Prog. (Dead	ofice :	TENENCH TENENCH		AUG.	9 hrs	for inc	d. prodes
Dry Gas Well Press						ι	3852	[dď	ls.	to e	st	ab.	24 hr.	SCC pot	d. prod _{вы} . • of m}—Си. fe.
Casing Head Gas P														Vinex minor	
Braden Head (8-															
Braden Head (Şizə													
								2116	<u></u>			367	¥		
PRODUCING FOR	MATI	X 100:	AVI Pou	ckle-	Lime		Top	3773	3.3	Bott	om .	377	7.1 TC	TAL DEPTH.	3777345
				(Name)	·····				-					1010	-3712
							CASIN		CORL) 		,			
OD Sire Wt.	Thds.	Where	Jts.	Feet	In.	Jts.	LEFT II	In.	- 1	KIND		Cond's	Sacks Used	CEMENTIN	Employed
8-5/8" 28 8	R		, ,			42	128	-1	H40	R2	RE	W A			
8-5/8" 32 8						2		Q 2		R2					
8-5/8" 32:8		6351				10	31	4 9					650	Hallibu	rton
5-1/2" 15 8	. D	-			Š	52	203	2 0	T55	R2	SS	A			
5-1/2" 15-8			(Lo	£_#76	71	33_	104	5_0		R2		A			
				t #14		36	73	q o		Rl	LW	A	200	Hallibu	rton
! !	l.			L	1 -	lar	and	5분	ca	sed_	to	der	cick f	loor)	
Used 1 - Li	<u> 5늴"</u>	OD	Lar	kin (idmo	nat	ion	<u> dui d</u>	19 %	Flo	at	Sho	9	,.	
Succentra	ner S	ec ai			Lengti	·		Р	erforate	d at		STATE	IT E	CEIVE	
Li	ner S	et a t	:		Lengtl	ı			erforate	d at			ONPO	RATION COM	UMUS-
Packer Set at				Size and	Kind								ALK	T	MISSION
Packer Set at				Size and	Kind		····				,	<u> </u>		∠5 1973	
,		,			SHOT	OR	ACID	TREA	TMEN	T REC	CO	SAIN CO	FDI.		
			FIRST				SECO	νD.				THIRD	Vichita	TON DIVES	} <i>P</i>
Date		6/	24/	49		fu	Rem	-la		<u> </u>				111345	
Acid Used Size Shot	50	00		G	als. DGX				Gals. Qts.				Gal. Qu		Gals. Qts.
Shot Between	37	73 Ft.	and	3777	Ft.		Ft. and		Ft.		F	t. and	, F	t. Ft. 4	and Ft.
Size of Shell										<u> </u>					
Put in by (Co.)	Do	owel	<u>1_</u> 1	nc.											
Length anchor	(x)	XF-l	<u>8_1</u> /	<u> -17)</u>						<u> </u>					
Distance below Cas'g	-	·		<u> </u>						ļ					
Damage to Casing or Casing Shoulder	<u></u>														
				SIC	NIFIC	INA	GEOL	OGIC	AL F	ORMA	ITI	ONS		•	
NAME	•	T	Тор	Botto	.		AS	4)IL				REMARKS	:
		74	241	1193	Fr	Deta.	T•		From	To	-				:
Heebner Sha			42 1	1211	 										
Toronto Lim Lansing Lim			42 1	1231	1			72/	931	358	51	Trois	י חחיי	and satu	retion
Lansing Lim Conglomerat			86†	145	5			7-	<u> </u>	טכע	-	T. C.T.	· nore	ميس عقدا	*********
Simpson Sha			58†	1527			, <u></u> ,	1			\neg		•	•	
Arbuckle Li			721	157		$\neg \uparrow$		37	1721	377	51	Fair	por.	and satu	ration
	***********			, - · · ·	1									and satu	
											-		· ·		
¥.					(CLEA	INING	OUT	REC	ORDS					
	DA	TE COM	MEN	CED	DATE CO	MPLE	TED	PRO	OD. BEF	ORE		PROD	AFTER	RE	MARKS
Îst	6	-28	-60	_	7-1	~ (:	ت	7:3	-147	WIN	12	nt a	2+WIR	See Reverse	for other details.
2nd														, ,	n n n .
3rd											Ĺ			, ,,	,, ,, ,,
4th							$\Box \Box$				oxdot			"."	. " "
				PLU	GGING	BA	CK AI	ND DI	EEPEN	ING I	REC	ORDS	<u></u>		
	Date	Commer	ered	Date C	ompleted	B	lo. Feet Pl ack or De	ugged	Pr	od. Befor	re .	P	rgd. After	REI	MARKS
1st														See Reverse	for other details.
2nd												_نـــا		" "	n n n
3rd			<u>·</u>											" "	, n n
4th														" "	# 11 H
			_												

(See Reverse for Record of Formation