Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Oil Occurrence of Associate Inc.	License Number: 20702
Operator Name: Oil Company of America, Inc.	License Number: 30762
Operator Address: 1200 Main St. Suite 101, Hays, KS. 67601	
Contact Person: Darrell Herl	Phone Number: (785) 625 - 3800
Permit Number (API No. if applicable): 15-051-04679-0001	Lease Name & Well No.: Herl # 5
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE_NE_SW
Settling Pit ✓ Drilling Pit	Sec. 13 Twp. 15 R. 18 East West
Workover Pit Haul-Off Pit	1478 Feet from North / South Line of Section
	3045 Feet from ✓ East / West Line of Section
	Ellis
	County
Date of closure: September 29, 2009	
Was an artificial liner used?	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
Lined with clay soil.	
Lined with day soil:	
Lined with day soil:	RECEIVED
Lined with day son:	RECEIVED
Lined with day son:	RECEIVED OCT 0 9 2009
Abandonment procedure of pit:	RECEIVED OCT 0 9 2009 KCC WICHTA
	RECEIVED OCT 0 9 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED OCT 0 9 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED OCT 0 9 2009 KCC WICHITA
Abandonment procedure of pit:	OCT 0 9 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.),
Abandonment procedure of pit: Allowed contents to air dry and back-filled.	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.),
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she isAgent	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.),
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she isAgent	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.),
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she is	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.), e best of his /her knowledge and belief.
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she isAgent	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she is	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she is	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.), e best of his /her knowledge and belief. Signature of Applicant or Agent
Abandonment procedure of pit: Allowed contents to air dry and back-filled. The undersigned hereby certifies that he / she is	OCT 0 9 2009 KCC WICHITA for Oil Company of America, Inc. (Co.), the best of his /her knowledge and belief. Signature of Applicant or Agent October 2009 Link Manually