## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: Town Of I Community	Lienza
Town OII Company, Inc.	License Number: 6142
Operator Address: 16205 West 287th St. Paola, Kansas 66071	
Contact Person: Lester Town	Phone Number: (913 ) 294 - 2125
Permit Number (API No. if applicable): 15-045-21535-00-00	Lease Name & Well No.: Johnson 1-09
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	SE - SW - SW - NW
Settling Pit Drilling Pit	Sec. 1 Twp. 15 R. 20 X East West
Workover Pit Haul-Off Pit	2805 Feet from North / X South Line of Section
•	4890 Feet from X East / West Line of Section
	County
Date of closure: 8-20-09	
Was an artificial liner used? Yes X No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?	
·	·
Used drilling mud	RECEIVED
Used drilling mud	RECEIVED AUG 2 6 2000
Used drilling mud	RECEIVED AUG 2 6 2009
Used drilling mud  Abandonment procedure of pit:	RECEIVED AUG 2 6 2009 KCC WICHITA
· .	RECEIVED AUG 2 6 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED AUG 2 6 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED AUG 2 6 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED AUG 2 6 2009 KCC WICHITA
Abandonment procedure of pit:	RECEIVED AUG 2 6 2009 KCC WICHITA  for Town Oil Company, Inc. (Co.),
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that XX/ she is Agent	for Town Oil Company, Inc. (Co.),
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that XX/ she is Agent	for Town Oil Company, Inc. (Co.),
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that XX/ she is Agent	for Town Oil Company, Inc. (Co.),
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that XX/ she is Agent	forTown Oil Company, Inc. (Co.), the best of his /her knowledge and belief.  Lette
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that Na/she is Agent a duly authorized agent, that all information shown hereon is true and correct to the Call  Subscribed and sworn to me on this day of	for Town Oil Company, Inc. (Co.), the best of his /her knowledge and belief.  Lette Journ  Signature of Applicant of Agent  August 2009
Abandonment procedure of pit:  Air dried and filled with dirt.  The undersigned hereby certifies that Na/she is Agent a duly authorized agent, that all information shown hereon is true and correct to the Call  Subscribed and sworn to me on this day of	forTown Oil Company, Inc. (Co.), the best of his /her knowledge and belief.  Lette