KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

Form CDP-4 April 2004 Form must be Typed

CLOSURE OF SURFACE PIT

Operator Name: Barnett Oil/ Winfred Barnett	License Number: 8333
Operator Address: 2303 70th Rd Humboldt, Ks. 66748	
Contact Person: Monty Barnett	Phone Number: (620) 473 - 3005
Permit Number (API No. if applicable): API 15-207-27 447 Ø 000	Lease Name & Well No.: Barnett #12
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>NW _ SE _ NW</u>
Settling Pit ✓ Drilling Pit	Sec. 4 Twp. 26 R. 17
Workover Pit Haul-Off Pit	1340 Feet from North / South Line of Section
	Feet from East / West Line of Section
	County
Date of closure: October 5, 2009	
Was an artificial liner used? Yes No	
If no, how were the sides and bottom sealed to prevent downward migration of the pit contents? Bentonite	
Bortonito	
	RECEIVED KANSAS CORPORATION COMMISSION
	RECEIVED KANSAS CORPORATION COMMISSION OCT 19 2009
Abandonment procedure of pit:	OCT 1 9 2009 CONSERVATION DIVISION
	OCT 19 2009
Abandonment procedure of pit:	OCT 1 9 2009 CONSERVATION DIVISION
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED BARNET	CONSERVATION DIVISION WICHITA, KS To BARNETT OIL (Co.).
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED BARNET a duly authorized agent, that all information shown hereon is true and correct to the	CONSERVATION DIVISION CONSERVATION DIVISION WICHITA, KS To BARNET OL (Co.), be best of his /her knowledge and belief.
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED BARNET a duly authorized agent, that all information shown hereon is true and correct to the	CONSERVATION DIVISION CONSERVATION DIVISION WICHITA, KS To BARNET OL (Co.), be best of his /her knowledge and belief.
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED RARNET a duly authorized agent, that all information shown hereon is true and correct to the Warnfust	CONSERVATION DIVISION WICHITA, KS To BARNETT OIL (Co.).
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED BARNET a duly authorized agent, that all information shown hereon is true and correct to the	CONSERVATION DIVISION CONSERVATION DIVISION WICHITA, KS To BARNET OL (Co.), be best of his /her knowledge and belief.
Abandonment procedure of pit: Air Dry-Backfill The undersigned hereby certifies that he / she is WINFRED RARNET a duly authorized agent, that all information shown hereon is true and correct to the Warnfust	CONSERVATION DIVISION CONSERVATION DIVISION WICHITA, KS To BARNET OL (Co.), best of his /her knowledge and belief.