To:		API NUMBER	15-133-D1674-C	<u> </u>
STATE CORPORATION COMMISSION		SW SW NE	Sec/Twp/Rge <u>33-28-21E</u>	
Wichita State Office Bldg PLUGGING SECTION 130 S. Market, Room 2078 Wichita, Kansas 67202		3182 (GPS)		
		2380 (GPS)		
TECHNICIAN'S PLUGGING REPORT		Lease/Well#	Vanleeuwen GPS #04	
Operator License # 101		County	Neosho	
Operator: State Of Kansas Fee F	und	Well Total Depth	450 (est)	feet
Name & Dent/Vanleeuwen Leas	se Project	Production Pipe:	2 Size F	eet375
Address		Surface Casing:	4.5 Size F	eet NA
AB oil well XXXXXX Gas Well	SW	D Well/ Input Well	D 8	& A
Other well as hereinafter indicated	:			
Plugging Contractor: Kepley We	ll Service, LLC		Lic	c. # <u>33749</u>
Address: 19245 Ford Road, Cha	nute, Kansas 66720			
Company to plug at: Hour:	Day	25	Month:	9 2008
Plugging proposal received from:	Mike Kepley			
Company Name:			Phone: KAI	RECEIVED NSAS CORPORATION COMA
Were: Clean well to TD and the	hen pump full of ceme	ent thru cement strir	ıg.	OCT 16 2008
				- TOTA DIVISION
· .	Plugging Proposal R	eceived by:	Alan M. Dunning	CONSERVATION DIVISION WICHITA, KS
	Plugging Proposal R	eceived by:	Alan M. Dunning TECHNI	ICIAN
Plugging attended by Agent:	All	Part	TECHNI	WICHITA, KS
Plugging attended by Agent: Operations Completed: Hour:		Part	TECHNI	ICIAN
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report:	All Day 360' of the 1" pipe ar	Part 25 nd packer were remo	Month: Dived. A 1" cement s	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well wa	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well wa	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we	All Day 360' of the 1" pipe ar s pumped full of cem	Part 25 and packer were remotent from btm to top to	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we location restored. Remarks: Control #20080018-03	All Day 360' of the 1" pipe ar s pumped full of cem ere used to plug well.	Part 25 nd packer were removent from btm to top to the well was cut of	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well wa of 21 sacks of portland cement we location restored. Remarks: Control #20080018-03 (If additional december)	All Day 360' of the 1" pipe ar s pumped full of cem ere used to plug well.	Part 25 nd packer were removent from btm to top to the well was cut of	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was
Plugging attended by Agent: Operations Completed: Hour: Actual Plugging Report: then lowered to 350'. The well was of 21 sacks of portland cement we location restored. Remarks: Control #20080018-03	All Day 360' of the 1" pipe ar s pumped full of cem ere used to plug well.	Part 25 nd packer were removent from btm to top to the well was cut of	Month: Dived. A 1" cement string	ICIAN one XXXXXX 9 2008 string was