

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Francis Oil & Gas, Inc. Address 905 Palace Bldg., Tulsa 3, Okla.
(Applicant)

Lease (Farm Name) Marcotte Well No. 1

Well Location Approx. C S/2SW/4 NW/4 Sec. 2 Twp. 10S Rge. 20 (E)-(W)

County Rooks Field Name (if any) Marcotte

Total Depth 3885' Oil Gas Dry Hole

Was well log filed with application? Yes . If not, explain: _____

Date and hour plugging is desired to begin Immediately

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully and exceptions desired. _____

(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

W.J. Hall Address 513 E. 3rd, Ellinwood, Kansas

Name of Plugging Contractor _____

Address _____

Invoice covering assessment for plugging this well should be sent to _____

Francis Oil & Gas, Inc. Address 905 Palace Bldg., Tulsa 3, Okla.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
11-18-55
1955

Samuel President
Applicant or Acting Agent

Date November 16, 1955

CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC 2 YLO R 20
BOOK PAGE 12 LINE 31



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

November 18, 1955

Well No.	1
Lease	Marcotte
Description	C S/2 SW NW 2-10-20W
County	Rooks
File No.	17-31

Francis Oil & Gas, Inc.
 905 Palace Building
 Tulsa 3, Oklahoma

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr.

Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor