

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

RECEIVED
STATE CORPORATION COMMISSION
7-19-73
JUL 19 1973
CONSERVATION DIVISION
Wichita, Kansas

Lease Owner K & G Oil Company

Address Drawer 368, Plainville, Kansas

Lease (Farm Name) Sparks Well No. B-4

Well Location C N2 NW SW Sec. 2 Twp. 10 Rge. 20 W (E) (W)

County Rooks Field Name (If Any) Berland

Total Depth 3862 Oil Well Gas Well Input Well SWD Well D & A

Well Log filed with application yes or Well Log filed with Plugging Supervisor

Date and hour plugging is desired to begin July 25 10:00 p.m.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Darrel Kelso

Address Chase, Ks., P. O. Box 176

Plugging Contractor Kelso Pipe Pulling Co. License No. 683

Address P. O. Box 176, Chase, Kansas

Invoice covering assessment for plugging this well should be sent to Fender Pipe & Supply, Inc.

Address Box 302, Russell, Kansas

and payment will be guaranteed by applicant.

Signed: *Darrel Kelso*
Applicant or Acting Agent

Date: July 17, 1973

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

July 19, 1973

WELL PLUGGING AUTHORITY

Well No.	B-4
Lease	Sparks
Description	C N/2 NW SW 2-10-20W
County	Rooks
Total Depth	3862
Plugging Contractor	Kelso Pipe Pulling Co.


K & G Oil Company
Box 368
Plainville, Kansas 67663

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Leo Massey Box 582 Hays, Kansas
is hereby assigned to supervise the plugging of the above
named well.