

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner The Bovaird Supply Company

Address P.O. Box 2590, Tulsa, Oklahoma

Lease (Farm Name) Renner Well No. 8

Well Location SW NE NW Sec. 5 Twp. 10 Rge. (E) 20 (W)

County Rooks Field Name (If Any) _____

Total Depth 3823' Oil Well X Gas Well _____ Input Well _____ SWD Well _____ D & A _____

Well Log filed with application yes or Well Log filed with Plugging Supervisor _____

Date and hour plugging is desired to begin July 17, 1969

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Jack Anthony

Box 897 Address Great Bend, Kansas

Plugging Contractor PIPE PULLERS, INC. License No. 462

Address Box 486, Ellinwood, Kansas

Invoice covering assessment for plugging this well should be sent to Pipe Pullers, Inc.

Box 486 Address Ellinwood, Kansas

and payment will be guaranteed by applicant.

Signed: Dean Wells E.R.
Applicant or Acting Agent
Dean Wells

Date: July 14, 1969

*RECEIVED
39-08-69*

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

500 Insurance Bldg.

212 N. Market

WICHITA, KANSAS 67202

July 16, 1969

RECEIVED
STATE CORPORATION COMMISSION
SEP 8 1969
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING AUTHORITY

Well No.	8
Lease	Renner
Description	SW NE NW 5-10-20W
County	Rooks
Total Depth	3823
Plugging Contractor	[REDACTED]

Bovaird Supply Company
Box 2590
Tulsa, Oklahoma 74101

Glenn & Smith Pipe Pullers

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,

J. Lewis Brock
J. Lewis Brock, Administrator

Mr. Leo Massey Box 582 Hays, Kansas

is hereby assigned to supervise the plugging of the above named well.