## Kansas Corporation Commission Oil & Gas Conservation Division

Form CDP-4 April 2004 Form must be Typed

## **CLOSURE OF SURFACE PIT**

Operator Name: T-N-T ENGINEERING, INC.	License Number: 33699
Operator Address: 3711 MAPLEWOOD STE 201 WICHITA FALLS, TX 76308-2101	
Contact Person: JOHN BERRYHILL	Phone Number: ( 940 ) 691 - 9157 EXT 106
Permit Number (API No. if applicable): 15-009-25,165-00-00	Lease Name & Well No.: Rexroat #3
Type of Pit:	Pit Location (QQQQ):
Emergency Pit Burn Pit	<u>S/2</u> _ <u>S/2</u> _ <u>NW</u>
Settling Pit	Sec. 14 _Twp. 17 _R. 13 East
Workover Pit Haul-Off Pit	2297 Feet from 🗸 North / 🗌 South Line of Section
	1037 Feet from East / West Line of Section
	BARTON County
Date of closure: 10/21/09  Was an artificial liner used? Yes No  If no, how were the sides and bottom sealed to prevent downward migration of the pit contents?  Native clay & fresh drill mud	
Native day & iresh dhii mud	
Native clay & fresh drill mud	RECEIVED
Native clay & fresh drill mud	RECEIVED
Abandonment procedure of pit:	OCT 2 9 2009
	OCT 2 9 2009
Abandonment procedure of pit:	OCT 2 9 2009
Abandonment procedure of pit:	OCT 2 9 2009
Abandonment procedure of pit:  Haul free fluids, let cuttings dry, backfill as soon as possible as pos	OCT 2 9 2009  KCC WICHITA  for
Abandonment procedure of pit:  Haul free fluids, let cuttings dry, backfill as soon as possit  The undersigned hereby certifies that he / she is Rickey Popp	OCT 2 9 2009  KCC WICHITA  for
Abandonment procedure of pit:  Haul free fluids, let cuttings dry, backfill as soon as possible.  The undersigned hereby certifies that he / she is	oct 2 9 2009  KCC WICHITA  for
Abandonment procedure of pit:  Haul free fluids, let cuttings dry, backfill as soon as possit  The undersigned hereby certifies that he / she is Rickey Popp	OCT 2 9 2009  KCC WICHITA  for
Abandonment procedure of pit:  Haul free fluids, let cuttings dry, backfill as soon as possible.  The undersigned hereby certifies that he / she is	oct 2 9 2009  KCC WICHITA  for